

Submit 1 Copy To Appropriate District  
Office  
District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S St Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St Francis  
Santa Fe, NM 87505

RECEIVED  
FEB 16 2010  
NMOCD ARTESIA

Form C-103  
October 13, 2009

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-30671
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator THE EDMAR COMPANY, L.L.C.		6. State Oil & Gas Lease No. L-6517
3. Address of Operator 400 W ILLINOIS AVE., SUITE 1610, MIDLAND, TX 79701		7. Lease Name or Unit Agreement Name POLAR BEAR STATE
4. Well Location Unit Letter <u>K</u> : <u>1,860</u> feet from the <u>SOUTH</u> line and <u>1,820</u> feet from the <u>WEST</u> line Section <u>36</u> Township <u>16S</u> Range <u>27E</u> NMPM County <u>EDDY</u>		8. Well Number <u>1</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) RKB 3547.5		9. OGRID Number 165255
		10. Pool name or Wildcat DOG CANYON, GRAYBURG GAS

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

13 3/8" csg @ 400', cmt'd w/ 563 sx, circulated  
8 5/8" 32# csg @ 1,500' w/ 725 sx, circulated  
4 1/2" 10.5# csg @ 1,802' w/ 250 sx, TOC 380' calculated  
perforations 1,671'-1,679'

1. Set CIBP @ 1,621'. Circulate hole w/ mud and pump 25 sx C cmt on CIBP.  
base of salt @ - 1,560' cmt plg. 50' below & 50' above salt. TAG.
2. 25 sx C cmt 450-350'. Surface casing shoe plug. TAG
3. Circulate 15 sx C cmt 60' to surface. RDMO.
4. Cut off wellhead & anchors, install dry hole maker.  
- TAG  
60' - surface

**Notify OCD 24 hrs. prior  
To any work done.**

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Laura Navarro*

TITLE LAND DEPARTMENT

DATE 02-12-10

Type or print name LAURA NAVARRO E-mail address: edmar\_79701@yahoo.com PHONE: (432)-686-8888  
For State Use Only

APPROVED BY:

*John Hawker*

TITLE

Approval Granted providing work  
is complete by 5/15/2010

DATE 2/15/2010

Conditions of Approval (if any):