Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED

OMB No 1004-0137 Expires July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.						5 Lease Senal No NM-045276 6. If Indian, Allottee or Tribe Name		
							7 If Unit or CA/Agreement, Name and/or No	
SUBMIT IN TRIPLICATE - Other instructions on page 2								
1. Type of Well						NA .		
	Oil Well Ga	s Well	Other P&A	MAR 02 2010		8 Well Name and No		
2 Name of 0	Operator			NMOCD ARTESIA		Preston Federal #7		
Yates Pe	troleum Corporation					9 API Well No		
3a Address		10040		No (include area code)		30-015-27908		
105 S. 4th Str., Artesia, NM 88210 575-748-1471 10 Field and Pool or Exp 4 Location of Well (Footage, Sec., T., R, M., OR Survey Description) South Dagger Dr.								
							11 County or Parish, State	
660'FSL & 1930'FEL of Section 35-T20S-R24E (Unit O, SWSE)						Eddy County, New Mexico		
	12 CHECK APPROP				NOTICE, RE			
TYPE OF SUBMISSION TYPE OF ACTION								
Γ	7	Acidize	D	Pecpen	Production (Start/Resume)	Water Shut-Off	
	Notice of Intent	Alter Casi	ng []F	racture Treat	Reclamation		Well Integrity	
Х	Subsequent Report	Casing Re	pair N	lew Construction	Recomplete		Other	
L	_Subsequent Report	Change Pi	lans X	lug and Abandon	Temporarily	Abandon		
	Final Abandonment Notice	Convert to	o Injection P	lug Back	Water Dispos	sal		
	NU BOP. Set a 7" 1 Tagged CIBP at 760 Did not tag any cem cement at 7546'. Tagged up at 7546', cement. Set RBP at 7518'. F to 7464'. Pumped 3 to 500 psi, held for 1 Pumped plug.	OK alpha CIBI 12'. No cemer ent. RIH with 8' high. Spot Packer at 7500 7 bbls. Teste	P at 7604' with 3 at on CIBP. Test another CIBP are ted 150 sx Class by Pumped 50 b d to 500 psi, goo	.5' cement on to ted to 1500 psi. nd set at 7554'. s "H" cement pl bls. Tubing on od. Dumped 21	op. Spotted 100 Tagged CIE ug. WOC 41 vacuum. Mo 0 bbls down M wanted to	0 sx Class "H" BP. Spotted 15 hrs. Tagged u oved RBP to 7 backside. Loa pump another	cement plug. 50 sx Class "H" p at 7546' - no 483' and packer aded up. Tested 25 sx plug. ging of the well bore.	
	certify that the foregoing is true	and correct			Sur	face restoration	is completed.	
Name (<i>(Printed∕Typed)</i> Tina Hi	uerta		_{itle} Regula	itory Complia	ınce Şupervişo	ונבט בעט טבעעט	
	, -	1		illo Trogalo	nory Compile	AUULT	TLD FOR KEGUK	
Signature	1 June	hierta	٥ ٥	ate Februa	ary 17, 2010			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE FEB. 2 4, 2010								
Approved by Title							PEB /4 2010	
Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office							\$ (hm)	
which would	entitle the applicant to conduct	operations thereon					U OF LAND MANAGEMENT	
	C Section 1001 and Title 43 U titious or fraudulent statements				williully to make t	to any department of	Hancalonion Finace Plates C	

Yates Petroleum Corporation Preston Federal #7 Section 35-T20S-R24E Eddy County, New Mexico Page 2

Form 3160-5 continued:

- 2/9/10 Tagged cement plug at 7520'. Pumped 50 bbls. Pumped 130 bbls. Broke circulation. Pumped 25 sx Class "H" cement plug at 7520'. TOC at 7383'. Did not have to tag. Pumped 260 bbls. Spotted 30 sx Class "C" cement plug at 5972'. TOC at 5788'. Did not have to tag. Spotted 35 sx Class "C" cement plug at 5062'.
- 2/10/10 Tagged cement plug at 4862'. Spotted 25 sx Class "C" cement at 2520'. TOC at 2367'. Did not have to tag. Spotted 25 sx Class "C" cement plug at 2260'. TOC at 2107'. Did not have to tag. Spotted 25 sx Class "C" cement plug at 1119'. WOC 2 hrs. Tagged plug at 935'. Circulated cement from 392' to surface. Pumped 65 sx. Topped well off with cement.
- 2/15/10 Dug out cellar. Cut off wellhead. Installed dry hole marker. Filled cellar back in. Dug out anchors. Cleaned location. <u>WELL IS PLUGGED AND ABANDONED.</u>

Regulatory Compliance Supervisor

February 17, 2010