1. Type of Well	
S. Well Name and JACKSON	reement, Name and/or No.
BURNETT OIL CO., INC. 3a. Addres@01 CHERRY STREET, SUITE 1500 4. Location of Well (Footage, Sec., T. P., M., or Survey Description) UNIT G, 1980' FNL, 1980' FEL, SEC 25, T17S, R30E-SURF & BTM HOLE 11. County or Paris EDDY COI 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHI TYPE OF SUBMISSION Acidize Acidize Deepen Acidize Deepen Acidize Deepen Acidize Practure Treat Reclamantion Well Integr Change Plans Change Plans Plug and Abandon Plug Back Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work an if the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of a Attach the food under which the work will be performed or provide the Bond No. on file with BLIAMIJA. Required subsequent report following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a F testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamantion, have been electromized that the site is ready for final inspection. 3/04/2010 Notify BLM -Terry Wilson and NMOCD-Randy Dade to begin final P&A on well bore. 3/08/2010 MIRU, RIH w/6-1/4" bit w/7" csg scraper on tbg to 3030'. POOH. 3/09/10 RIH w/pkr & tbg, se circulation, POOH w/tubing & pkr. RIH w/cmt retainer & set @ 3032'. Pump 50 sks Class C cmt, pump 2 PO retainer, WOC. 3/10/10 RIH, tag @ 2882', circ 9.5# mud gel. POOH w/tbg, perf 4 SPF @ 1530', RII 1168'. Establish circ, pump 50 sks Class C cmt- all witnessed by BLM's Bob Hoskinson. 3/11/10 Release pkr, F 9.5# mud gel. POOH w/tbg & pkr. RUW/L, perf 4 SPF @ 60', establish circ, pump 25 sks Class C cmt, Class C w/2% CaCl cmt. Circulate cement to surface. Cement fell back 25'. 3/16/10 Fill w/Redi-mix to surface. Well bore: SPlugged and Abandoned.	
BURNETT OIL CO., INC. 3a. Addres@01 CHERRY STREET, SUITE 1500 3b. Phone No. (include area code) UNIT #9 FORT WORTH, TX. 76102-6881 (817) 332-5108 10. Field and Pool. 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) UNIT G, 1980' FNL, 1980' FEL, SEC 25, T17S, R30E- SURF & BTM HOLE 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHING TYPE OF SUBMISSION TYPE OF SUBMISSION Acidize Deepen Production (Start/Resume) Water Shut Plug and Abandon Temporarily Abandon Acidize Deepen Plug and Abandon Temporarily Abandon Convert to Injection Plug Back Water Disposal 3. Describe. Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and if the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of Attach the Boad under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent report following completion of the involved operations. If the operation results in a multiple completion or recompleted in a new interval, at testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamantion, have been a determined that the site is ready for final inspection.) 3/04/2010 Notify BLM -Terry Wilson and NMOCD-Randy Dade to begin final P&A on well bore. 3/08/2010 MIRU, RIH w/6-1/4" bit w/7" csg scraper on tbg to 3030'. POOH. 3/09/10 RIH w/pkr & tbg, se circulation, POOH w/tubing & pkr. RIH w/cmt retainer & set @ 3032'. Pump 50 sks Class C cmt, pump 20 retainer, WOC. 3/10/10 RIH, tag @ 2882', circ 9.5# mud gel. POOH w/tbg, perf 4 SPF @ 1530', RIH v168'. Establish circ, pump 50 sks Class C cmt. all witnessed by BLM's Bob Hoskinson. 3/11/10 Release pkr, F. 9.5# mug gel. POOH w/tbg & pkr. RU W/L, perf 4 SPF @ 60', establish circ, pump 25 sks Class C cmt, Class C w/2% CaCl cmt. Circulate cement to surface. Cement fell back 25'. 3/16/10 Fill w/Red	
30-015-04:	B #10
UNIT #9 FORT WORTH, TX. 76102-6881 (817) 332-5108 [10. Field and Pool, GRAYBURG UNIT G, 1980' FNL, 1980' FEL, SEC 25, T17S, R30E- SURF & BTM HOLE [11. County or Paris EDDY COl. 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER TYPE OF SUBMISSION [12. Check APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER TYPE OF SUBMISSION [13. Change Plans [14. Change Plans [15. Check Appropriate Production (Start/Resume)] Water Shute Subsequent Report [15. Change Plans [15. Check Appropriation (clearly state all pertinent details, including estimated starting date of any proposed work and if the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of a feesing has been completed. Final Abandomment Notices shall be filled only after all requirements, including reclamantion, have been content that the site is ready for final inspection.] 3/04/2010 Notify BLM -Terry Wilson and NMOCD-Randy Dade to begin final P&A on well bore. 3/08/2010 MIRU, RIH w/6-1/4" bit w/7" csg scraper on tbg to 3030'. POOH. 3/09/10 RIH w/pkr & tbg, se circulation, POOH w/tubing & pkr. RIH w/cmt retainer & set @ 3032'. Pump 50 sks Class C cmt, pump 2 PO retainer, WOC. 3/10/10 RIH, tag @ 2882', circ 9.5# mud gel. POOH w/tbg, perf 4 SPF @ 1530', RIH 168'. Establish circ, pump 50 sks Class C cmt- all witnessed by BLM's Bob Hoskinson. 3/11/10 Release pkr, P. 9.5# mug gel. POOH w/tbg & pkr. RU w/L, perf 4 SPF @ 60', establish circ, pump 25 sks Class C cmt, 24/66/10 Fill w/Redi-mix to surface. Well bore is Plugged and Abandoned.	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) UNIT G, 1980' FNL, 1980' FEL, SEC 25, T17S, R30E- SURF & BTM HOLE 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHING TYPE OF SUBMISSION TYPE OF SUBMISSION Acidize Deepen Production (Start/Resume) Alter Casing Fracture Treat Reclamantion Well Integr Change Plans Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work an If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of a Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent report following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a F testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamantion, have been a determined that the site is ready for final inspection.) 3/04/2010 Notify BLM -Terry Wilson and NMOCD-Randy Dade to begin final P&A on well bore. 3/08/2010 MIRU, RIH w/6-1/4" bit w/7" csg scraper on tbg to 3030'. POOH. 3/09/10 RIH w/pkr & tbg, se circulation, POOH w/tubing & pkr. RIH w/cmt retainer & set @ 3032'. Pump 50 sks Class C cmt, pump 2 PO retainer, WOC. 3/10/10 RIH, tag @ 2882', circ 9.5# mud gel. POOH w/tbg, perf 4 SPF @ 1530', RIH 168'. Establish circ, pump 50 sks Class C cmt- all witnessed by BLM's Bob Hoskinson. 3/11/10 Release pkr, F 9.5# mug gel. POOH w/tbg & pkr. RU W/L, perf 4 SPF @ 60', establish circ, pump 25 sks Class C cmt, Class C w/2% CaCl cmt. Circulate cement to surface. Cement fell back 25'. 3/16/10 Fill w/Redi-mix to surface. Well bore is Plugged and Abandoned.	,
UNIT G, 1980' FNL, 1980' FEL, SEC 25, T17S, R30E- SURF & BTM HOLE 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHING TYPE OF SUBMISSION TYPE OF SUBMISSION Acidize Deepen Production (Start/Resume) Acidize Deepen Reclamantion Well Integrated Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and if the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of a Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent report following completed. Final Abandonment Notices shall be filed only after all requirements, including reclamantion, have been a determined that the site is ready for final inspection.) 3/04/2010 Notify BLM -Terry Wilson and NMOCD-Randy Dade to begin final P&A on well bore. 3/08/2010 MIRU, RIH w/6-1/4" bit w/7" csg scraper on tbg to 3030'. POOH. 3/09/10 RIH w/pkr & tbg, se circulation, POOH w/tubing & pkr. RIH w/cmt retainer & set @ 3032'. Pump 50 sks Class C cmt, pump 2 PO retainer, WOC. 3/10/10 RIH, tag @ 2882', circ 9.5# mud gel. POOH w/tbg, perf 4 SPF @ 1530', RIH 168'. Establish circ, pump 50 sks Class C cmt- all witnessed by BLM's Bob Hoskinson. 3/11/10 Release pkr, F 9.5# mug gel. POOH w/tbg & pkr. RU W/L, perf 4 SPF @ 60', establish circ, pump 25 sks Class C cmt, Class C w/2% CaCl cmt. WOC 4 hrs. Release pkr, perf @ 565'. RIH vestablish circ, pump 50 sks Class C cmt- all witnessed by BLM's Bob Hoskinson. 3/11/10 Release pkr, F 9.5# mug gel. POOH w/tbg & pkr. RU W/L, perf 4 SPF @ 60', establish circ, pump 25 sks Class C cmt, Class C w/2% CaCl cmt. Circulate cement to surface. Cement fell back 25'.	or Exploratory Area G JACKSON -QN-SA
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHING TYPE OF SUBMISSION Acidize	*
TYPE OF SUBMISSION Acidize	JNTY, N.M.
Acidize Deepen Production (Start/Resume) Water Shut Alter Casing Practure Treat Reclamantion Well Integrated Subsequent Report Casing Repair New Construction Recomplete Other Alter Disposal Casing Repair New Construction Recomplete Other Abandon Convert to Injection Plug Back Water Disposal Subsequent Notice Casing Repair New Construction Recomplete Other Abandon If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of a Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent report following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a F testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamantion, have been a determined that the site is ready for final inspection.) 3/04/2010 Notify BLM -Terry Wilson and NMOCD-Randy Dade to begin final P&A on well bore. 3/08/2010 MIRU, RIH w/6-1/4" bit w/7" csg scraper on tbg to 3030'. POOH. 3/09/10 RIH w/pkr & tbg, se circulation, POOH w/tubing & pkr. RIH w/cmt retainer & set @ 3032'. Pump 50 sks Class C cmt, pump 2 PO retainer, WOC. 3/10/10 RIH, tag @ 2882', circ 9.5# mud gel. POOH w/tbg, perf 4 SPF @ 1530', RIH 168'. Establish circ, pump 50 sks Class C cmt- all witnessed by BLM's Bob Hoskinson. 3/11/10 Release pkr, 9.5# mug gel. POOH w/tbg & pkr. RU w/L, perf 4 SPF @ 60', establish circ, pump 25 sks Class C cmt, Class C w/2% CaCl cmt. Circulate cement to surface. Cement fell back 25'. 3/18/10 Fill w/Redi-mix to surface. Well bore is Plugged and Abandoned.	R DATA
Notice of Intent Alter Casing Fracture Treat Reclamantion Well Integration Casing Repair New Construction Recomplete Other Mel Integration Casing Repair New Construction Recomplete Other Casing Repair New Construction Recomplete Other Casing Repair New Construction Recomplete Other Design Recomplete Other De	
Subsequent Report Casing Repair New Construction Recomplete Other	Off
Plug and Abandon Temporarily Abandon Temporarily Abandon Temporarily Abandon Convert to Injection Plug Back Water Disposal The proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work an If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of a Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent report following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a F testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamantion, have been a determined that the site is ready for final inspection.) 3/04/2010 Notify BLM -Terry Wilson and NMOCD-Randy Dade to begin final P&A on well bore. 3/08/2010 MIRU, RIH w/6-1/4" bit w/7" csg scraper on tbg to 3030'. POOH. 3/09/10 RIH w/pkr & tbg, se circulation, POOH w/tubing & pkr. RIH w/cmt retainer & set @ 3032'. Pump 50 sks Class C cmt, pump 2 PO retainer, WOC. 3/10/10 RIH, tag @ 2882', circ 9.5# mud gel. POOH w/tbg, perf 4 SPF @ 1530', RIH vestablish circ, pump 50 sks Class C cmt- all witnessed by BLM's Bob Hoskinson. 3/11/10 Release pkr, 9.5# mug gel. POOH w/tbg & pkr. RU W/L, perf 4 SPF @ 60', establish circ, pump 25 sks Class C cmt, Class C w/2% CaCl cmt. Circulate cement to surface. Cement fell back 25'. 3/16/10 Fill w/Redi-mix to surface. Well bore is Plugged and Abandoned.	ly
Change Plans	PINAL
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work an If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent report following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a F testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamantion, have been a determined that the site is ready for final inspection.) 3/04/2010 Notify BLM -Terry Wilson and NMOCD-Randy Dade to begin final P&A on well bore. 3/08/2010 MIRU, RIH w/6-1/4" bit w/7" csg scraper on tbg to 3030'. POOH. 3/09/10 RIH w/pkr & tbg, se circulation, POOH w/tubing & pkr. RIH w/cmt retainer & set @ 3032'. Pump 50 sks Class C cmt, pump 2 PO retainer, WOC. 3/10/10 RIH, tag @ 2882', circ 9.5# mud gel. POOH w/tbg, perf 4 SPF @ 1530', RIH 168'. Establish circ, pump 50 sks Class C cmt- all witnessed by BLM's Bob Hoskinson. 3/11/10 Release pkr, 9.5# mug gel. POOH w/tbg & pkr. RU W/L, perf 4 SPF @ 60', establish circ, pump 25 sks Class C cmt, Class C w/2% CaCl cmt. Circulate cement to surface. Cement fell back 25'. 3/16/10 Fill w/Redi-mix to surface. Well bore is Plugged and Abandoned.	.,
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work an If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of a Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent report following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a F testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamantion, have been a determined that the site is ready for final inspection.) 3/04/2010 Notify BLM -Terry Wilson and NMOCD-Randy Dade to begin final P&A on well bore. 3/08/2010 MIRU, RIH w/6-1/4" bit w/7" csg scraper on tbg to 3030'. POOH. 3/09/10 RIH w/pkr & tbg, se circulation, POOH w/tubing & pkr. RIH w/cmt retainer & set @ 3032'. Pump 50 sks Class C cmt, pump 2 PO retainer, WOC. 3/10/10 RIH, tag @ 2882', circ 9.5# mud gel. POOH w/tbg, perf 4 SPF @ 1530', RIH vestablish circ, pump 50 sks Class C cmt- all witnessed by BLM's Bob Hoskinson. 3/11/10 Release pkr, F 9.5# mug gel. POOH w/tbg & pkr. RU W/L, perf 4 SPF @ 60', establish circ, pump 25 sks Class C cmt, Class C w/2% CaCl cmt. Circulate cement to surface. Cement fell back 25'. 3/16/10 Fill w/Redi-mix to surface. Well bore is Plugged and Abandoned.	
3/17/2010 Installed required P&A marker. 3/22/2010 BLM notified to reclaim and reseed. Location is re-	5 sks cmt below retaine I w/pkr & tbg, set pkr @ v/pkr, set @ 238'. RIH & tag @ 467', circ WOC 2 hrs, pump 75 sk
and the second s	y tor BEW inspection.
We have notified Central Valley Electric to remove their one (1) electric pole from the location.	
Reclamation Due 9/12/10 Liability under bond Surface restoration	ing of the well bore. is retained until s completed.
14. I hereby certify that the foregoing is true and correct.) Name (Printed/Typed)	(
MARK A. JACOBY Title ENGINEERING MANAGER	, FOD DEOODD

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United OFFICE

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

CARL SBAD FIELD OFFICE

Title

Office

UNITED STATES

DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT'

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

FORM APPROVED

OMB No. 1004-0137

Expires: July 31, 2010

MAR 2 9 2010

5. Lease Serial No.

NMNM2747

6. If Indian, Allottee or Tribe Name

Form 3160-5

(August 2007) VEL

APR -1 2010

Mark A.

applicant to conduct operations thereon.

(Instructions on page 2)

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.