UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0135 Expires. July 31, 2010

PROVED 004-0135 731, 2010



SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

. Lease Serial No. NMNM69369

	, , ,
6.	If Indian, Allottee or Tribe Name

SUBMIT IN TRIE	7 If Unit or CA/Ag	greement, Name and/or No.					
Type of Well ☐ Gas Well ☐ Other				2 9 2010	8. Well Name and N SUNDANCE 1	No. FEDERAL 4 /	
Name of Operator Contact: LINDA GOOD CHESAPEAKE OPERATING, INC. E-Mail: linda.good@chk.com				ARTESI	9. API Well No. 30-015-28176	3 /	
3a. Address 3b. Phone No. (in P.O. BOX 18496 P.O. BOX 18496 Ph: 405-935-4 OKLAHOMA CITY, OK 73154-0496					10. Field and Pool,	or Exploratory E DELAWARE /	
4. Location of Well (Footage, Sec., T. Sec 1 T24S R31E SESE 740F			11. County or Paris				
12. CHECK APPR	OPRIATE BOX(ES) TO) INDICATE N	ATURE OF	NOTICE, RE	PORT, OR OTH	IER DATA	
TYPE OF SUBMISSION			ТҮРЕ О	F ACTION			
Notice of Intent Subsequent Report Final Abandonment Notice 13. Describe Proposed or Completed Ope If the proposal is to deepen directiona Attach the Bond under which the wor following completion of the involved testing has been completed. Final Abdetermined that the site is ready for fit CHESAPEAKE, RESPECTFU CANYON PER THE FOLLOW 1. MIRU PU. NU BOP. Unload 2. RIH w/4 3/4" bit, drill collars 3. RIH w/packer to 8,200', just leak. POH w/packer. (Note: it liner). 4. Rig up wire line co. Perforal	ally or recomplete horizontally, k will be performed or provide operations If the operation re andonment Notices shall be fill nal inspection.) LLY, REQUESTS PERM ING PROCEDURE. d, rack, and tally 2-7/8" on 2 7/8" tbg. Check PE above perfs. Pressure to large section of casing it te Brushy Canyon:	Plug an Plug B Plug B It details, including give subsurface loc the Bond No. on fi sults in a multiple c ed only after all req ISSION TO WO 6.5# L-80 tubing BTD of 8,555'. F est casing. If te	re Treat onstruction and Abandon ack estimated startin ations and meas le with BLM/BL ompletion or rec uirements, inclu RKOVER AN POH w/bit.	Reclama Recompl Recompl Tempora Water D Recompl Water D Recompletion in a nding reclamation Required Subsompletion in a nding reclamation REE ATT CONDITION	lete arily Abandon isposal oposed work and apprical depths of all pe ssequent reports shall new interval, a Form 3 n, have been complete ACHED FO	Well Integrity Other Workover Operation proximate duration thereof. The filed within 30 days 3160-4 shall be filed once ed, and the operator has	
14. Thereby certify that the foregoing is	Electronic Submission #	82786 verified by KE OPERATING,	the BLM We INC., sent to	II Information the Carlsbad	System		
Name (Printed/Typed) LINDA GOOD Ti				Title SR. REGULATORY COMPLIANCE SPEC			
Signature (Electronic Submission) Da				2010			
	THIS SPACE FO	OR FEDERAL	OR STATE	OF NOT DE	OVFD		
Approved By Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent to conduct which would entitle the applicant to conduct the applicant	itable title to those rights in the	s not warrant or e subject lease	Title Office	MAR 2	2 6 2010 n Winkler	Date	
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	· · · · · · · · · · · · · · · · · · ·					t or agency of the United	

Additional data for EC transaction #82786 that would not fit on the form

32. Additional remarks, continued

8,155-8,174' (19') (one shot every other foot) (10 holes) 8,193-8,225' (32') (one shot every other foot) (16 holes) 8,236-8,244' (8') (one shot per foot) (8 holes) Set CBP @ 8,255'.

- 5. RIH w/packer to 8,250'. Pump 5 bbl 15% inhibited HCL to pickle tubing. Circulate acid out with clean 2% KCL. Spot 15% NEFE acid across perfs. Pull packer up to 8,050'. Set packer and acidize Brushy Canyon perfs w/5,000 gal 15% NEFE acid dropping 50 perfs balls through out job. Swab back acid and test. Drop packer down through perfs to knock off perf balls. POH w/packer.
- 6. If warranted, frac Brushy Canyon per frac recommendation (anticipate 30 BPM down casing, 100,000# of sand).
- 7. RIH w/bit & collars on tbg. Drill out CBP @ 8,225'. Clean out to PBTD of 8,555'. POH w/bit.
- 8. RIH w/production tbg & rods. POP from entire Brushy Canyon Section 8,155' 8,282'. RD MO.

(CHK PN 890549)

Chesapeake Operating Company NM-69369: Sundance 1 Federal #4

API: 30-015-28176

Eddy County, New Mexico

RE: Add Pay NOI – Conditions of Approval

There is to be no surface disturbance beyond the existing pad. A closed loop system is to be used. H2S monitoring and protection equipment is to be on site.

2M BOP required. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.

If 4-1/2" liner to be run, sundry must be submitted and approved before casing is run and cemented.

Submit subsequent report and well test once work is completed.

DHW 032210