Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APPROVED OMB NO. 1004-0135

Expires: November 30, 2000

5. Lease Serial No.

NMNM62589

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

abandoned well. Use Form 3160-3 (APD) for such proposals.					
SUBMIT IN TRIPLICATE -	Other instructions	on reverse side	**********	1 1	APR = 8 2010 nit or CA/Agreement, Name and/or I
1. Type of Well X Oil Well Gas Well Other 2. Name of Operator					NMOCD ARTESIA Name and No. al 23 #16
OXY USA Inc. 3a. Address D. O. Boy 50250 Midland TV 70710	3b. Phone No. (include area code) -0250 432-685-5717			9. API Well No. 30-015-37341	
P.O. Box 50250, Midland, TX 79710-0250 432-685-5717 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) SL - 612 FNL 509 FEL NENE(A) Sec 23 T22S R31E BHL- 380 FNL 1980 FEL NWNE(B) Sec 23 T22S R31E				10. Field and Pool, or Exploratory Area Livingston Ridge Delaware 11. County or Parish, State Eddy NM	
12. CHECK APPROPRIATE TYPE OF SUBMISSION	BOX(ES) TO IND		NOTICE, REP		R OTHER DATA
Notice of Intent	Acidize	Deepen		n (Start/Res	nume) Water Shut-Off
Subsequent Report	Alter Casing Casing Repair Change Plans	Fracture Treat New Construction Plug and Abandon	Reclamati Recomple		Well Integrity Other Larredia Le
Final Abandonment Notice 13. Describe Proposed or Completed Operation (clear)	Convert to Injecti	on Plug Back	Water Dis	posal	Osind Febru

Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

See Attached

Title	Sr. Regulatory_A	malvst
Date	2(5(10	APPROVED
L OR STA	TE OFFICE USE	
Title		FEB Date 5 2010
or Office		WESLEY W. INGRAM
	L OR STA Title	Sr. Regulatory Date Z(5(10) L OR STATE OFFICE USE Title Office

Well name: Federal 23 #16 **API:** 30-015-37341

Remedial Squeeze Procedure:

1. TIH to retrieve RBP.

- 2. Perform cement squeeze job as follows: 500 bbls of 10 ppg brine water, 5 bbls fresh water spacer, 2500 gals FloChek, 5 bbls fresh water spacer and 400 sacks Premium Plus cement with 2% calcium chloride @ 14.8 ppg. WOC minimum 24 hrs.
- 3. Drill out cement, pressure test squeeze holes, if successful, rig down pulling unit, rig up drilling rig, continue drilling operations
- 4. If unsuccessful, based on results of pressure test, either repeat steps 2 & 3 or condition hole for casing patch. Notify BLM of results.
- 5. TIH and set Weatherford casing patch across perforations zone (Casing Patch is 20 ft long), see specifications attached. Wait 24 hr after setting patch per manufacture recommendations and test casing to 1500 psi, if casing test fails, a forward plan will be develop and submitted, otherwise move off WO rig and move in drilling rig to continue drilling production hole.

FEDERAL 23 016 (API 30-015-37341)

