Form 3160-5 UNITED STATES FORM APROVED (February 2005) DEPARTMENT OF THE INTERIOR OMB NO. 1004-0135 **BUREAU OF LAND MANAGEMENT** EXPIRES: March 31, 2007 OCD Artesia SUNDRY NOTICES AND REPORTS ON WELLS Lease Serial No. Do not use this form for proposals to drill or to re-enter an NMLC-065478-B abandoned well. Use Form 3160-3 (APD) for such proposa 6. If Indian, Allottee or Tribe Name SUBMIT IN TRIPLICATE 7. Unit or CA Agreement Name and No. APR **21** 2010 1a. Type of Well Oil Well Gas Well Other 8 Well Name and No. NMOCD ARTESIA 2. Name of Operator Falcon 3 G Federal 9 DEVON ENERGY PRODUCTION COMPANY, LP 9. API Well No. 3. Address and Telephone No. 30-015-35808 10. Field and Pool, or Exploratory 20 North Broadway, Oklahoma City, OK 73102-8260 405-552-8198 Red Lake; Glorieta-Yeso, NE 4. Location of Well (Report location clearly and in accordance with Federal requirements)\* 2110' FNL & 2310' FEL, Sec. 3-T18S-R27E, Unit "G" 11. County or Parish Eddy NM 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OS SUBMISSION TYPE OF ACTION Water Shut-Off Production (Start/Resume) Acidize Deepen ✓ Notice of Intent Well Integrity Reclamation Alter Casing Fracture Treat Subsequent Report **New Construction** Recomplete Other Casing Repair Plug and Abandon Temporarily Abandon Change Plans Final Abandonment Notice Water Disposal Convert to Injection ✓ Plug Back deepen directionally or recomplete honzontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the 3 ond No on file with BLM/BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection) Devon Energy Production Company, LP respectfully requests approval to plug back the Yeso and test the San Andres formation. 1. MIRU PU. POOH with rods and pump. NU BOP. POOH with tubing. 2. RU wireline. RIH with composite-bridge-plug and set at ~ 2900'. 3. RIH with perforating gun and perforate San Andres from 2212'-2766'; 1 spf, 0.38" holes; 31 shots. RD wireline. Frac perforations per recommendation. 5. RIH with slick gun and set composite bridge plug at ~ 2184'. Perforate upper San Andres from 1908'-2164'; 1 spf, 0.38" holes; 54 total shots. POOH with wireline and RD wireline. 6. Frac perforations per recommendation. RD and flow well back. 7. RU foam air unit and drill out composite bridge plug at ~ 2184'. Circulate hole clean and POOH. 8. RIH with tubing, rods, and pump. 9. RDMO PU. SEE ATTACHED FOR CONDITIONS OF APPROVAL Hereby certify that the foregoing is true and correct orvella Adams PR Name

\*See Instruction on Reverse Side

within its juriso

Title

Title

(This space for Federal or State Office use)

Approved by

Conditions of appro-





APR 2 0 2010

Dustin Winkler

CARL SBAD FIELD OFFICE

4/12/2010





Devon Energy Production Company, LP NMLC-065478-B – Falcon 3 G Federal #9 API: 30-015-35808 Eddy County, New Mexico

RE: Plug back/Recompletion - Conditions of Approval

There is to be no surface disturbance beyond the existing pad without prior approval. A closed loop system is to be used. H2S monitoring and protection equipment is to be on site.

- 1. OK
- 2. CIBP to be set at 3075'. Before production of the San Andres, proper plug back must be completed with 25sx of class C cement pumped on top of CIBP. (Perfs Glorietta)
- 3. OK
- 4. OK
- 5. OK
- 6. OK
- 7. OK
- 8. OK
- 9. OK

Submit subsequent report and completion report once work is completed.

DHW 042010

REMINDER – Operator should plan their schedule to allow for two weeks for proper review of any proposed operation.

WWI 042010