
Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APROVED OMB NO. 1004-0135 EXPIRES: March 31, 2007

	TICES AND REPORTS ON WELL	LS	OCD AN	5. Lease Serial No.	25. March 31, 2007
Do not use this form for proposals to drill or to re-enter an			 7	NMLC-065478-B	
abandoned well. Us	se Form 3160-3 (APD) for such p	propose ECEIVI		6. If Indian, Allottee	or Tribe Name
SI	UBMIT IN TRIPLICATE				
		MAY 12 20	10	7. Unit or CA Agree	ment Name and No.
1a. Type of Well 🔲 Ga	as Well Other	 		8 Well Name and N	Jo
2. Name of Operator		 NMOCD ARTI	ESIA 		on 3 K Federal 27
DEVON ENERGY PRODUC		9 API Well No			
3. Address and Telephone No.				30-015-3	36314
20 North Broadway, Oklahoma City, OK 73102-8260 405-552-8198				10. Field and Pool,	
Location of Well (Report location clearly and in accordance with Federal requirements)*					ike; Glorieta-Yeso
1895 FSL & 1410 FWL Sec 3 T18S R27E, Unit K				11. County or Parish State	
				Eddy NM	
12. CHEC	K APPROPRIATE BOX(s) TO IN	NDICATE NATURE OF NO	TICE, REPO	RT, OR OTHER DATA	'A
TYPE OS SUBMISSION TYPE OF ÁCTION					
☑ Notice of Intent	Acidize	Deepen	Productio	n (Start/Resume)	Water Shut-Off
	Alter Casing	Fracture Treat	Reclamat		Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomple		Other
Final Abandonment Notice	Change Plans Convert to Injection	✓ Plug and Abandon ☐ Plug Back	Water Dis	rily Abandon sposal	
13. Describe Proposed of Completed Operations (Calepen directionally or recomplete horizontally, give s	clearly state all pertinent details, and give pe	ertinent dates, including estimated of	date of starting an	y proposed work and approx	
nerval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection. Devon Energy Production Company, LP respectfully requests approval to plug back the Yeso and test the San Andres formation. MIRU PU. POOH with rods and pump. NU BOP. POOH with tubing. RU wireline. RIH with composite bridge plug and set at ~ 2700. RIH with perforating gun and perforate San Andres from 2236'-2467'; 1 spf, 0.38" holes; 45 shots. RD wireline. Frac perforations per recommendation. RIH with slick gun and set composite bridge plug at ~ 2180'. Perforate upper San Andres from 1914'-2142'; 1 spf, 0.38" holes; 45 total shots. POOH with wireline and RD wireline. Frac perforations per recommendation. RD and flow well back. RU foam air unit and drill out composite bridge plug at ~ 2180'. Circulate hole clean and POOH. RIH with tubing, rods, and pump. RDMO PU. SEE ATTACHED FOR CONDITIONS OF APPROVAL					
14 Nereby certify that the foregoing is to Signed (This space for Federal or State Office years)	Name Title	Norvella Adam Sr. Staff Edgineering Tech	nician	ED Date 2010	4/12/2010
Approved by Conditions of approval, if any: BUREAU OF LAND MANAGEMENT					
	TOPI SCHI KIN IMPLICIU ZI I ZAMINIMO II ZAMINIMO ZI ZAMINIMO ZAMINIMO ZI ZAMINIMO ZA	CARL	SBAD FIELD) ()FF1(;F	tements or representations to any matter
Title To U.S.C. Section 1001, makes it a crime for any person knowingly and willing to make any department of adentity of the Carles any hase. It also be the adentity of the Carles and t					

,	RODUCTION COMPANY LP			
Well Name: FALCON 3 K FEDERAL 27	Field: RED LAKE			
Location: 1895' FSL & 1410' FWL; SEC 3-T185-R27E	County: EDDY State: NM			
Elevation: 3565' GL	Spud Date: 7/10/08 Compl Date: 8/27/08			
API#: 30-015-36314 Prepared by: Ronnie Slack	Date: 6/17/09 Rev:			
11" Hole 8-5/8", 24#, J55, STC, @ 1,178' Cmt'd w/445 sx to surface	2-7/8" production tubing			
8/1/08 Frac w/15.5K# lite + 20 5K# 16/30	SN @ 3550'			
8/5/08: Reperf Yeso & acidized w/3K gals 15% HCI	EOMA @ 3580'			
8/8/08 Re-Frac Yeso w/15.5K# lite + 20 5K# 16/30 7-7/8" Hole 5-1/2", 15.5#, J55, LTC, @ 3,665'	3630' PBTD			



Devon Energy Production Company, LP NMLC-065478-B – Falcon 3 K Federal #27

API: 30-015-36314

Eddy County, New Mexico

RE: Plug back/Recompletion - Conditions of Approval

Notification: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

There is to be no surface disturbance beyond the existing pad without prior approval. A closed loop system is to be used. H2S monitoring and protection equipment is to be on site.

- 1. OK
- 2. CIBP to be set at 3035'. Before production of the San Andres, proper plug back must be completed with 25sx of class C cement pumped on top of CIBP. (Perfs Glorietta)
- 3. OK
- 4. OK
- 5. OK
- 6. OK
- 7. OK
- 8. OK
- 9. OK

Submit subsequent report and completion report once work is completed.

DHW 043010