

Submit 1 Copy To Appropriate District  
Office  
District I  
1625 N French Dr , Hobbs, NM 88240  
District II  
1301 W. Grand Ave , Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S St. Francis Dr , Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
October 13, 2009

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS )		WELL API NO. 30-015-37690
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		7. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Marbob Energy Corporation		7. State Oil & Gas Lease No.
3. Address of Operator P.O. Box 227, Artesia, NM 88211-0227		7. Lease Name or Unit Agreement Name VT 36 State
4. Well Location Unit Letter <u>D</u> : <u>480</u> feet from the <u>North</u> line and <u>330</u> feet from the <u>West</u> line Section <u>36</u> Township <u>19S</u> Range <u>25E</u> NMPM Eddy County		8. Well Number 1
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3451' GR		9. OGRID Number 14049
		10. Pool name or Wildcat Seven Rivers; Yeso

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: Completion Operations ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

5/4/10 MIRU.

5/5/10 Circulate hole clean. Tag PBDT @ 3314' Log from PBDT up to 600'. Perforate Yeso 3279-3283' (5). Acdz w/500 gal 15% NEFE.

5/7/10 Set CIBP @ 3265'. Perforate Yeso 3214-3218' (5). Acdz w/500 gal 15% NEFE acid.

5/11/10 Set CIBP @ 3192'. Perforate Yeso 2953-2957', 3034-3038', 3090-3094' (15). Acdz w/1500 gal 15% NEFE.

5/13/10 Frac w/71100# sand & 55127 gal fluid. ISIP 1645#, AIP 3037#, AIR 52 BPM.

5/17/10 Set 96 jts 2 7/8" 6.5# J-55 tbg @ 3164'.

5/18/10 Hang well on pump.

Spud Date:

4/4/10

Rig Release Date:

4/11/10

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Stormi Davis TITLE Production Assistant DATE 5/25/10

Type or print name Stormi Davis E-mail address: sdavis@marbob.com PHONE: 575-748-3303

For State Use Only

APPROVED BY: David Gray TITLE Field Supervisor DATE 6-1-10  
Conditions of Approval (if any):