Submit 1 Copy To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Re	Psources	Form C-103 October 13, 2009	
District I 1625 N French Dr., Hobbs, NM 88240	Energy, Willierars and Waterar Re	WELL AP	WELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIV	ISION 30-015-239		
District III	1220 South St. Francis D	La Indicate	Type of Lease TE ☐ FEE ☒	
1000 Rio Brazos Rd , Aztec, NM 87410 District IV	Santa Fe, NM 87505	L	1 & Gas Lease No.	
1220 S St Francis Dr , Santa Fe, NM 87505				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		CK TO A NDDUP U		
PROPOSALS)		8. Well Nu	Imber RECEIVED	
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator		55 9. OGRID	Number JUN - 8 2010	
2. Name of Operator Yates Petroleum Corporation		9. OGRID 025575	Number 3014 . 8 2010	
3. Address of Operator			ame or MNNOCD ARTESIA	
105 South Fourth Street, Artesia, NM 88210		Dagger Dra	nw; Upper Penn, North	
4. Well Location				
Unit Letter C: 660 feet from the North line and 1980 feet from the West line				
Section 19 Township 19S Range 25E NMPM Eddy County				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
3588'GR				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WORK ☐ ALTERING CASING ☐				
TEMPORARILY ABANDON				
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB			Deb 24 his. phoi	
DOWNHOLE COMMINGLE TO CATY Work done.				
OTHER:	ОТН	ER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
Yates Petroleum Corporation plans to plug and abandon this well as follows: 1. NU BOP. Rig up any safety equipment as needed. No casing recovery will be attempted. 2. Set a CIBP at 7726' with 35' cement on top. This will place a plug over open Canyon perforations. 3. Spot a 160' cement plug from 5378'-5538'. This will leave a plug across Wolfcamp top. 4. Spot a 140' cement plug from 3398'-3538'. This will leave a spacer plug in the 5-1/2" casing. 5. Spot a 150' cement plug from 1099'-1249'. This will leave a plug across intermediate casing shoe. WOC and tag plug, reset if necessary 6. Perforate at 450'. Tie on to casing and spot a 450' cement plug inside and outside casing from 0-450', do not displace cement. WOC and tag plug, reset if necessary. This will leave a plug across surface casing shoe to surface. 7. Remove all surface equipment and weld dry hole marker per regulations.				
Due to the volume of wells we currently have plans to plug, both State/Fee and Federal, Yates Petroleum respectfully requests a time frame of 1 year to have commenced plugging operations and for this notice of intent to be in affect				
Spud Date:	Rig Release Date:			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE TITLE Regulatory Compliance Supervisor DATE June 2, 2010				
Type or print name Tina Hue	erta E-mail address: tinah@y	vatespetroleum.com I	PHONE: <u>575-748-4168</u>	
For State Use Only				
APPROVED BY:	TITLE Approvat	Granted providing work	DATE 6/14/2010	
Conditions of Approval (if any):	Approval	eta hu C/14/20//	/ /	



