

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S St Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
June 19, 2008

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

JUN 16 2010

NMOC D ARTESIA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		WELL API NO. 30-015-30897
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Mack Energy Corporation		6. State Oil & Gas Lease No. VO-4861
3. Address of Operator P.O. Box 960 Artesia, NM 88210		7. Lease Name or Unit Agreement Name Southern Cross 20 State Com
4. Well Location Unit Letter <u>P</u> <u>1200</u> feet from the <u>South</u> line and <u>1100</u> feet from the <u>East</u> line Section <u>20</u> Township <u>18S</u> Range <u>24E</u> NMPM County <u>Eddy</u>		8. Well Number 1
11. Elevation (Show whether DR, RKB, RT, GR etc.) 3808' GR		9. OGRID Number 013837
		10. Pool Name or Wildcat Rio Penasco Wolfcamp

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIALWORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

Notify OCD 24 hrs. prior  
to any work done.

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Notify OCD 24 hours prior to starting plugging operations.

- 1) Set CIBP @ 5475' w/ 35' cmt cap on top.
- 2) Set 25sx cmt plug at 3800' (top of Abo)
- 3) Set 25sx cmt plug at 1750' (top of Glorieta)
- 4) TIH w/ tbg to 1270'. Set 10sx cmt plug (across 8 5/8" surface csg shoe) woc Tag 1276' - 1176'
- 5) TIH to 65' circ cmt to surface.
- 6) Install P & A marker

Spud Date:

3/25/2000

Rig Release Date:

4/19/2000

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Jerry W. Sherrell*

TITLE Production Clerk

DATE 6/8/10

Type or print name Jerry W. Sherrell

E-mail address: jerrys@mackenergycorp.com

PHONE: (575)748-1288

For State Use Only

APPROVED BY:

*[Signature]*

TITLE

DATE

6/14/2010

Conditions of Approval (if any):

Approval Granted providing work  
is complete by 8/14/2010

**Mack Energy Corporation**  
 Southern Cross 20 State Com #1  
 Sec. 20 T18S R24E  
 30-015-30897

**Before**

**After**

