

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-37425
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name SRO State Unit Com
8. Well Number 5H
9. OGRID Number 14049
10. Pool name or Wildcat WC; Bone Spring

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐	
2. Name of Operator Marbob Energy Corporation	
3. Address of Operator PO Box 227, Artesia, NM 88211-0227	
4. Well Location Unit Letter <u>M</u> : <u>660</u> feet from the <u>South</u> line and <u>330</u> feet from the <u>West</u> line Section <u>8</u> Township <u>26S</u> Range <u>28E</u> NMPM <u>Eddy</u> County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3107' GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: Completion Operations ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

5/12/10 MIRU WSU.

5/13/10 Drill out DVT. Circulate.

5/15/10 Tag PBTD @ 10857'. Perforate Bone Spring 10429', 10562', 10693' & 10826' (32).

5/20/10 Acdz 10429-10826' w/3991 gal 7 1/2% NEFE. Frac w/334229# sand & 331385 gal fluid. ISIP 1107#, MXTP 7678#, AIR 101.7 BPM. Set CFP @ 10313'. Perforate Bone Spring 9814', 9952', 10090' & 10228' (32). Acdz w/2283 gal 7 1/2% NEFE. Frac w/334682# sand & 319584 gal fluid. ISIP 1271#, MXTP 7075#, AIR 123.8 BPM. Set CFP @ 9714'. Perforate Bone Spring 9216', 9354', 9492' & 9630' (32). Acdz w/2039 gal 7 1/2% NEFE. Frac w/331384# sand & 319772 gal fluid. ISIP 1401#, MXTP 7115#, AIR 124.1 BPM.

5/21/10 Set CFP @ 9116'. Perforate Bone Spring 8618', 8756', 8894' & 9032'. Acdz w/1468 gal 7 1/2% NEFE. Frac w/325047# sand & 323108 gal fluid. ISIP 1234#, AIR 119 BPM. Set CFP @ 8544'. Perforate Bone Spring 8020', 8158, 8296' & 8434' (32). Acdz w/2883 gal 7 1/2% NEFE. Frac w/334479# sand & 320477 gal fluid. ISIP 1483#, MXTP 6907#, AIR 126.3 BPM. Set CFP @ 7944'. Perforate Bone Spring 7422', 7560', 7698' & 7836' (32). Acdz w/2311 gal 7 1/2% NEFE. Frac w/337539# sand & 321093 gal fluid. ISIP 1453#, MXTP 7109#, AIR 125.2 BPM. Set CFP @ 7346'. Perforate Bone Spring 6824', 6962', 7100' & 7238' (32). Acdz w/3738 gal 7 1/2% NEFE. Frac w/265370# sand & 312288 gal fluid. ISIP 1390#, MXTP 6500#, AIR 122.3 BPM.

5/25/10 to 6/7/10 Drill out CFP's @ 7346', 7944', 8544', 9116' & 9714'. Wash down to CFP @ 10313'. Start drlg. Lost circ as top of plug drld off. Observed stall on motor. Could not move uphole. Pipe stuck. Work pipe free. Pump N2 while rotating w/swivel. POOH. TIH w/grapple, O/S, BS & jars. Engage fish. TOOH w/fish.

6/8/10 Set 185 jts 2 7/8" 6.5# J-55 tubing @ 6011'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Stormi Davis TITLE: Production Assistant DATE: 6/22/10

Type or print name: Stormi Davis E-mail address: sdavis@marbob.com PHONE: (575) 748-3303

For State Use Only

APPROVED BY: David Gray TITLE: Field Supervisor DATE: 6-30-10

Conditions of Approval (if any):