		•				
Form 3160-5	United States			Form Approved		
(August 1999)	Department of the Interior			OMB No. 1004-0135		
Ruragu Of Land Management			•	Expires November 30, 2000 5. Lease Serial No.		
	Sundry Notices And Reports on Wells			NMLC029389A		
Do not use this form for proposals to drill or to re-enter an Abandoned well. Use form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name			
OCD-ARTESIA			7. If Unit or CA/Agreement, Name and/or No.			
SUBMIT IN TRIPLICATE - Other Instructions On reverse side			8. Well Name and No.			
1. Type of Well:			o. Well Name and No.			
☐ Oil Well ☐ Gas Well ☐ Other			Baish Federal #6			
2. Name of Operator			9. API Well No.			
Pecos Production Company			30-015-3090200S2			
3. Address of Operator 3b. Phone No. (Include area code) 400 W Illinois, Ste 1070, Midland, Texas 79701 (432) 620-8480			10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Shugart, North Strawn Reef- 11. County or Parish, State			
1. Document of West (1 conage, see., 1., 12, 11., or but vey Description)				Tr. County of Farisit, State		
660' FWL & 1980' FNL, Sec 9, T18S, R31E			Eddy Co, NM			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
Type Of Submission	Type Of Action					
	☐ Acidize 🗹	Deepen	☐ Produ	ction (Start/Resume) 🛚 Water Shut-Off		
Notice of Intent	☐ Alter Casing ☐	Fracture Treat	☐ Recla	mation Well Integrity		
✓ Subsequent Report☐ Final Abandonment Notice	☐ Casing Repair ☐	New Construction	☐ Recor	Recomplete Other		
	☐ Change Plans ☐	Change Plans				
	•	Plug Back	-	Water Disposal		
proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 11/03/03 = MIRU PU. NU BOP. 11/04/03 = RIH w/5 ½" CIBP & set @ 8595'. 11/05/03 = Test lines to 4000 psi. Set cmt retainer @ 5526'. Test the to 3000 spi. Cmt sqz w/75 sxs CI C w/FLA & 75 sxs CI C Neat. Stung out & reverse out w/FW. 11/08/03 = Tag CIBP @ 8593'. Press test sqzd perfs, csg & CIPB to 1100# - ok. 11/11/103 = NIU WH. 11/19/03 = MIRU. 11/12/03 = TIH w/whipstock (set whipstock top- 8581'/btm- 8595'). Run gyro. Cut 16" on window. Mill & trip. 11/22/03 = Cut window from 8594'-8600'. Mill & trip. 11/22/03 = Cut window from 8594'-8600'. Mill & trip. 11/23/03 = Drill & srvy. 12/08/03 = TD @ 11,100'. TOOH for logs & RU loggers. 12/09/03 = Ag GR-CNL-ZDL-DLL (11,086'-8600'). 12/10/03 = Ran 3 ½" csg 9.3# L80 (tot 2832') w/liner hanger (2853'). Top of liner @ 8250' & set @ 11,100'. Cmt w/250 sxs 15:61:11 + additives. Reverse out 10s sxs. WOC. Test liner 1200 psi = Okay. Rig Rlsd, 12/11/03. 12/16/03 = MIRU Completion Unit. 12/18/03 = RIH w/ GR-CCL & CBL tl & ran ff10,958'-8150'. PBTD @ 10,958'. 12/20/03 = Rih w/ GR-CCL & CBL tl & ran ff10,958'-8150'. PBTD @ 10,958'. 12/20/03 = Acidize perfs (10718'-10887') w/5000 gals 15% NEFE acid.						
12/21/03 - Perf Strawn Perfs 1/10,718*-10,887* (2 SPF - 36 holes). 12/23/03 - Acidize perfs (10718*-10887*) w/5000 gals 15% NEFE acid. LES BABYAK PETROLEUM ENGINEER						
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)						
Dora Lara		Title	Eng. Asst	t.		
Signature Don Zan		Date	1/1/04			

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or Certify that the applicant holds legal or equitable title to those rights in the subject lease Which would entitle the applicant to conduct operations thereon.

Title

Office

Date