State of New Mexico Form C-103 Submit 3 Copies To Appropriate District Office-Energy, Minerals and Natural Resources Revised May 08, 2003 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 30.015.22010 District II OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. District III STATE X 1000 Rio Brazos Rd., Aztec, NM 87410 FEE Santa Fe, NM 87505 District IV 6. State Oil & Gas Lease No. 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Empire Abo Unit 'H' DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well No. 1. Type of Well: Oil Well X Gas Well Other 293 **BECEIVED** 2. Name of Operator 9. OGRID Number BP America Production Company 000778 10. Pool name or Wildcat 3. Address of Operator P.O. Box 1089 Funice NM 88231 OCD-ARTESIA Empire Abo 4. Well Location 1249 S 50 Unit Letter _feet from the ___ feet from the line line and Section Township Range **NMPM** County EDDY 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON [ALTERING CASING PERFORM REMEDIAL WORK REMEDIAL WORK \mathbf{x} **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. **PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE** CASING TEST AND COMPLETION CEMENT JOB OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. TD: 6378' PBD: 6170' PERFS: 5692-6156' 09.29.03: MURUPU. NDWH. NUBOP. SET CIBP @ 6170'. RUN TDT LOGS & PERF AS FOLLOWS: 5692-94, 5706-08, 5734-38, 5742-44, 5762-64, 5776-5806, 5816-20, 5832-44, 5856-60, 5869-73, 5894-97, 5936-40, 6000-03, 6010-12, 6050-71, 6080-88, 6094-97, 6102-04, 6107-09, 6130-42, 6150-56', 2 JSPF, 285 HOLES. ACIDIZE W/6000 GALS 15% HCL W/425 1.1. BALL SEALERS. RIH & RECOVER BALLS. RIH W/ 2-3/8" TBG. SET @ 6112'. HANG WELL ON. RETURN TO PRODUCTION I hereby certify that the information above is true and complete to the best of my knowledge and belief. Staff Support TITLE_ SIGNATURE. 02.10.04 _DATE_ Type or print name Telephone No.

TITLE

SUPERVISOR, DISTRICT II

DATE

(This space for State