<u>District 1</u> 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District IV

District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

Date: 12/8/2010

* Attach Additional Sheets If Necessary

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe NM 87505

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

	Server or a comment	General Control of the Control		, Si	aina r	C, INIVI 073	03			y paragramana and analysis in			
30-015	-025	41	Rel	ease Notific	catio	n and Co	rrective A	ction	1				
MLB1034337841						OPERATOR			X Initial Report Final Repor				
Name of Company Melrose Oil & Gas /84860						Contact Garrett Newton							
Address 1905 West Sears Ave., Artesia, New Mexico 88210						Telephone No. 575-513-0230							
Facility Name Artesia State Unit #46						Facility Type WIW							
Surface Owner Mineral Owner						Lease No.							
<u> </u>													
TT 1. T	T a	T	 	· · · · · · · · · · · · · · · · · · ·		N OF REI		l = .a					
Unit Letter F	Section 3	Township 18S	Range 28E	Feet from the 2310'	North East	South Line Feet from the 2267'		East/West Line West		County EDDY			
1 3 183 286 2510				Last		220)	West		LDD1				
			T.	atitude <u>32.7777</u>	7	Longitude	104 1649						
			L										
				NAT	TURE	OF RELI							
Type of Rele							ne Recovered 15 bbls						
Source of Release Flow line										1 Hour of Discovery 010 1:00AM			
			11/20/2010 1.00ANI				U I.UUAIVI						
Was Immedia	ate Notice (If YES, To Whom?										
		X	NMOCD after hours answering system.										
By Whom? Garrett Newton						Date and Hour 11/26/2010 am.							
Was a Watercourse Reached? ☐ Yes ☐ No						If YES, Vo	lume Impacting t	he Wate	ercourse.				
											- fran 1.	A pers pers	
If a Watercou	rse was Im	pacted, Descri	be Fully.*	•						REC	1	VED	
										UEC	Λa	2010	
									l	DEC	v j	2010	
	_									SIMACC	D AI	RTESIA	
Describe Cause of Problem and Remedial Action Taken.* The flow line located north of the Artesia Unit #46 ruptured. The flow line was taken out of service and then repaired.												11	
ine flow line	located noi	nn of the Artes	sia Unit #	46 rupturea. The	now iin	ie was taken ot	it of service and t	nen rep	airea.				
		and Cleanup A			- A I	ing The effect		mad ta	ha aiahte a	:	at lana	her forter	
				of the well near the acted area was ex									
				ork plan for the co				о прри	voa Bona	vaste alope	,		
71 1		<u> </u>			•								
				is true and compled/or file certain re									
				e of a C-141 repo									
				investigate and re									
or the environ	ment. In ac	ddition, NMO	CD accept	tance of a C-141									
federal, state,	or local law	vs and/or regul	lations.										
		1	OIL CONSERVATION DIVISION										
Signature	100		The					,				:	
	74 1 2 72 7					Approved by I	District Supervise Signed By	r//	il				
Printed Name	: Garrett Ne	wton		T			Signed By	11/4	DKMIN	ucoe_			
Title: Field Su	mervisor				Approval Date	OFF A A A	F	xpiration E	late.				
THO. TICK DO	-per 11801					The same of the	DEC 09 21	טוט '	p.i.uiioii L				
							-	1.				-	
E-mail Addres	E-mail Address: gnewton@pvtnetworks.net						Conditions of Approval:				Attached		
Date: 12/8/20	10		D	Phone: 575-513-02	230	REMEDIATION per OCD Rules and							

Guidelines. SUBMIT REMEDIATION \perp

Phone: 575-513-0230