

Submit 1 Copy To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
October 13, 2009

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-29927 22927
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name EMPIRE ABO UNIT
8. Well Number #F-364
9. OGRID Number 873
10. Pool name or Wildcat EMPIRE ABO


SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Apache Corporation	
3. Address of Operator 303 Veterans Airpark Ln. Midland, TX 79705	
4. Well Location Unit Letter _____ : _____ 1550 _____ feet from the _____ N _____ line and _____ 750 _____ feet from the _____ E _____ line Section 34 Township 17S Range 28E NMPM County EDDY	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3675.6 GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input type="checkbox"/>
DOWNHOLE COMMINGLE <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>
OTHER: COMPL TO UPPER ABO <input checked="" type="checkbox"/>	OTHER: <input type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1) MIRU unit, RIH w/4 3/4 bit
- 2) CO to +/-6004', RIH to 5930' circ well clean, POOH
- 3) Set CIBP above top perf
- 4) Perf. 5866-5872, 5879-82, 5885-87, 5892-94, 5898-5900, 5903-06, 5910-13 w/2 SPF
- 5) Acidize new perfs from 5866-5913, make production equip decision after swab results
- 6) Perf. 5822-24, 5826-28, 5834-39, 5842-44, 5846-48, 5853-56w/2 SPF
- 7) Set BP above top perf,
- 8) Acidize new perfs 5822-5856
- 9) Recover RBP, RWTP on rod pmp



Spud Date: 1979

Rig Release Date: 1979

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Katie Kauffman

TITLE Engineering Tech

DATE: 2/2/2011

Type or print name Katie Kauffman

E-mail address: katie.kauffman@apachecorp.com

PHONE: 432.818.1065

For State Use Only

APPROVED BY: Donald Gray
Conditions of Approval (if any):

TITLE Field Supervisor

DATE 2-8-11

subent Sundries to include tbg. detail - size, wt., grade, # of jts. in well