## OCD-ARTESIA

Form 3160-5 (February 2005)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007

5. Lease Serial No.

NMNM-54856

SUNDRY NOTICES AND REPORTS ON WELLS

6. If Indian, Allottee or Tribe Name

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					O. II matan, Anottee of Tibe Name		
SUBMIT IN TRIPLICATE – Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well							
☐ Oil Well ☐ Gas Well ☐ Other					8. Well Name and No. Dickens 29 Federal 4H		
2. Name of Operator Devon Energy Production Company, L.P.					9. API Well No. 30-015-38285		
3a. Address 20 North Broadway, Oklahoma City, OK 73102			Phone No. (include area code)		10. Field and Pool or Exploratory Area		
405-228-8973					Dog Canyon; Wolfcamp (17970)		
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)					11. Country or Parish, State		
840' FNL & 330' FEL of Sec 29 T16S R28E					Eddy County, NM		
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT O							TA
TYPE OF SUBMISSION TYPE OF ACTION							
✓ Notice of Intent	Acidize Deepe		en Produ				Water Shut-Off
	Alter Casing	Fracti	are Treat	Recla	ımation		Well Integrity
Subsequent Report	Casing Repair	New !	Construction	Reco	mplete	$\checkmark$	
			and Abandon		orarily Abandon		Spudder rig to set
Final Abandonment Notice	Convert to Injection	Plug	Back	Wate	r Disposal		surface casing
testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)  Devon Energy Production Company, LP request a to set surface casing with a rig from Ashton Oilfield Services. The rig plat is attached. This rig will be used only to set the surface casing and will leave the location once the surface casing has been run and cemented. Another rig will drill the remainder of the wellbore.  The BLM will be contacted prior to commencing drilling operations. The surface casing will be run and cemented back to surface as per the approved APD. The well will be secured with a cap welded onto the surface casing. Another rig will be on location to drill the remainder of the wellbore within 60 days after the Ashton rig has left the location. The BLM will be notified when the Ashton rig moves off location. The surface casing will be tested as per BLM Onshore Orders No.2 when the drilling rig moves on location.  SEE ATTACHED FOR CONDITIONS OF APPROVAL  RECEIVED  MAR 2 2 2011  NMOCD ARTESIA							
Name (Printed/Typed)  Spence Laird  Title Regulatory Analys							
Operior Laire			Title Regulatory Arialyst				
Signature Spend (and)			Date 03/15/2011		Γ		PPROVED
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						<u> </u>	
Approved by			Title			1.1	MAR 1 6 2011
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.						BUREA BUREA	S/ Chris VValls U OF LAND MANAGEMENT
Title 18 U.S.C. Section 1001 and Title 43 fictitious or fraudulent statements or representations.				and willfully t	o make to any depar		

## Dickens 29 Federal 4H 30-015-38285 Devon Energy Production Company, L. P. 16 March 2011 Conditions of Approval

- 1. Surface disturbance beyond the originally approved pad must have prior approval.
- 2. Option Setting surface casing with Ashton Rig
  - a. Notify the BLM when removing the Ashton Oilfield Services Rig.
  - b. Notify the BLM when moving in the H&P Flex Rig. Rig to be moved in within 60 days of notification that Ashton Oilfield Services Rig has left the location. Failure to notify or have rig on location within 60 days will result in an Incident of Non-Compliance.
  - c. Once the H&P Flex Rig is on location, it shall not be removed from over the hole without prior approval unless the production casing has been run and cemented or the well has been properly plugged. If the drilling rig is removed without approval an Incident of Non-Compliance will be written and will be a "Major" violation.
  - d. BOP/BOPE test to be conducted per Onshore Oil and Gas Order No. 2 as soon as H&P Flex Rig is rigged up on well. CIT for the surface casing shall be performed and results recorded on subsequent sundry pressure to be 1200 psi.

**CRW 031611**