

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

MAY 26 2009

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

30-015-21309

nkmw 1109433487

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Seely Oil Company	20497	Contact	David L. Henderson
Address	815 W. 10 <sup>th</sup> St., Ft. Worth, TX 76102		Telephone No.	817-332-1377
Facility Name	Stevens Federal #2		Facility Type	

Surface Owner	Federal	Mineral Owner		Lease No.	NM 0384576
---------------	---------	---------------	--	-----------	------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	35	17S	30E	660	North	1980	East	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	Approx 5 bbls	Volume Recovered	0
Source of Release	Flowline failure	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	May 14, 2009 unknown time
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Mr. Tim Gumm	Date and Hour	Unknown		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Unknown persons turned a pumping unit on which caused a flowline failure. Approximately 5 bbls of oil was pumped out of the leak. Seely Oil Company proposes to remove and dispose of the affected soil.

Describe Area Affected and Cleanup Action Taken.\*

An area of about 20 feet square around the wellhead and a thin stream about 18" wide by 55' was affected.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: David L. Henderson	Approved by District Supervisor 	
Title: Executive Vice President	Approval Date: 4/4/11	Expiration Date:
E-mail Address: dhenderson@seelyoil.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5/21/2009 Phone: 817-332-1377	REMEDATION per OCD Rules and Guidelines. SUBMIT REMEDIATION PROPOSAL BY: 5/4/11	

\* Attach Additional Sheets If Necessary

2RP-689

(1)