Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources Hobbs. NM 88240		October 13, 2009 WELL API NO.
District II	OH CONCEDIATION DIVICION		30-015-29460
District III	District III 1220 South St. Francis Dr.		5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505		.001796	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name Poker Lake Unit
PROPOSALS.) 1. Type of Well: Oil Well		8. Well Number ₁₂₇	
2. Name of Operator BOPCO, L.P.		9. OGRID Number	
3. Address of Operator P.O. Box 2760		260737 10. Pool name or Wildcat	
Midland, TX 79702		Poker Lake (Delaware)	
4. Well Location			2000 (2000)
	feet from the South		
Section 2		Range 30E	NMPM CountyEddy
	11. Elevation (Show whether Di 3349' GL	K, KKB, KI, GK, eic.)	
the state of the s	02.5		Dispersion of the control of the con
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF IN	TENTION TO:	l SUR	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	「JOB □
DOWNHOLE COMMINGLE			
OTHER: Convert to SWD well	X	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
BOPCO, L.P. respectfully wishes to convert this well to a SWD well.			
BOPCO, L.P. has been authorized to utilize this well to inject produced water for disposal puposes as of June 28, 2010 by			
Administrative Order No. SWD-1222. The following procedure outlines the SWD conversion process:			
Drill out plugs down to 7,000'. Set two plugs from 7,700' to 7,990' and from 6,200' to 6,300'. Cmt in 5-1/2" csg string to 6,100'. Add			
Delaware zones within the permitted interval of 4,268'-5,928' Port and frac stimulate at 5,766' to 5,786' and 5,628' to 5,648' in one			
12,000# stage utilizing LiteProp 125 14/30. Place well on injection not exceeding 854 psi. (I) TUBNICA INFO & POSITION OF PREVEN MINT (B) PROVIDED WON COMPLETION. (C) PREVEN WITHIN 1070 OF WIPER ZONE (B) OCH NUTIFIED OF INITIAL MIT REST. APR 15 2011			
1) TUBING INFO	a fortrom of	becker w	MST DEOCHUED
BE PROUDED	WYON COMPLETED	2-15	RECEIVED
@ PRIVER WITH	tin 100 of upper	ANT DAT	APR 15 2011
3 DED NOTTE	ar of willac.	WILL REAL	·
Spud Date: 03/30/1997	Rig Release I	Date: 04/23/1997	NMOCD ARTESIA
(4) INITAL THE	MUST BE PERFORME	D REGINE	MUETTON CON CELUR.
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
	. 4	, c	
SIGNATURE Maluri	Inay TITLE Regul	atory Clerk	DATE 04/13/2011
·			
Type or print name Valerie Truax	E-mail addre	ss: vltruax@basspet.	com PHONE: (432)683-2277
For State Use Only	/ - 2	. 6	11
APPROVED BY: (If any):	Vae TITLE CO	mpubrus C	PACER DATE 4/20/11