

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised May 08, 2003

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-26232
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator ConocoPhillips Company		6. State Oil & Gas Lease No. K - 3271
3. Address of Operator 4001 Penbrook St., Odessa, TX 79762		7. Lease Name or Unit Agreement Name James A
4. Well Location Unit Letter <u>P</u> : <u>500</u> feet from the <u>South</u> line and <u>660</u> feet from the <u>East</u> line Section <u>2</u> Township <u>22-S</u> Range <u>30-E</u> NMPM County <u>Lea</u>		8. Well Number 007
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3223' GL		9. OGRID Number
		10. Pool name or Wildcat Cabin Lake - Delaware

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: Run Permanent ESP <input checked="" type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

(1) 1/20/2004:

MIRU DDU. RU PUMP TRUCK TO KILL WELL. PUMP 40 BBLS 10# BRINE.
ND WELLHEAD. NU BOP. SHUT DOWN.



*** CONTINUED ON BACK ***

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Celeste G. Dale TITLE Regulatory Analyst DATE 2/13/04

Type or print name Celeste G. Dale Telephone No. (432) 368-1667
(This space for State use)

APPROVED BY _____ TITLE _____ DATE _____

Conditions of approval, if any:

Continued:

James "A" State #7

(2) 1/21/2004: BLEED WELL DOWN. RU CENTRILIFT. POOH W/ 2-7/8 TUBING AND PUMP LAY DOWN PUMP. CHECK 6 JTS OF TAIL PIPE BELOW PUMP. FOUND FRAC SAND IN BULL PLUG ON BOTTOM OF TAIL PIPE. RD CENTRILIFT. SHUT DOWN.

(3) 1/22/2004: BLEED WELL DOWN. POOH W/ KILL STRING. RU CENTRILIFT. PU MOTOR AND CAVIN DESANDER. TRIED TO MAKE UP SWADGE. COULD NOT, THREADS ON MOTOR BASE WERE BAD. LAY DOWN MOTOR AND SEND IN FOR REPAIRS. RIH W/ KILL STRING. SHUT DOWN.

(4) 1/23/2004: BLEED WELL DOWN. POOH W/ KILL STRING. RU CENTRILIFT TO RUN PUMP IN HOLE. RIH W/ BULL PLUG, 6 JTS TBG, CAVINS DESANDER, MOTOR, SEAL, INTAKE, PUMP AND 213 JTS 2-7/8 TBG. PUMP INTAKE @ 6715'. RU PUMP TRUCK, PUMPED 40 BBLs 10# BRINE. ND BOP, NU WELLHEAD. ELECTRIFY WELL AND CHECK PUMP. PUMPING GOOD. CLEAN LOCATION. RDMO.