

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

WELL API NO.  
30-005-63363

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
V-5649

7. Lease Name or Unit Agreement Name:  
Quiniela AXQ State

RECEIVED

8. Well No.  
1 NOV - 7 2003

9. Pool name or Wildcat  
OCD-ARTESIA  
Wildcat Precambrian

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☐ Gas Well ☒ Other ☐

2. Name of Operator  
Yates Petroleum Corporation

3. Address of Operator  
105 S. 4<sup>th</sup> Street Artesia, NM 88210

4. Well Location

Unit Letter E : 1980 feet from the North line and 660 feet from the West line

Section 5 Township 10S Range 26E NMPM Chaves County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3769'GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

10/20/03 - Reached TD 5950' at 4:00 PM.

10/21/03-10/31/03 - Losing partial returns. Fish in hole. Could not retrieve fish. Obtained verbal plugback instructions from Van Barton.

11/1/03 - Set plugs as follows:

Plug #1 4729'-4629' - 35 sx

Plug #2 4282'-4182' - 35 sx

Plug #3 2200'-2100' - 35 sx

Plug #4 1950'-1850' - 35 sx

Plug #5 1180'-1080' - 70 sx (in/out plug set across casing shoe at 1130'. Tagged plug at 1054'.)

Plug #6 500'-400' - 35 sx

Plug #7 100'-surface - 30 sx

Released rig at 5:00 AM 11/2/03. Dry hole marker installed. WELL IS PLUGGED AND ABANDONED. FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tina L. Huerta TITLE Regulatory Compliance Supervisor DATE November 4, 2003

Type or print name Tina L. Huerta

Telephone No. 505-748-1471

(This space for State use)

APPROVED BY [Signature] TITLE Field Rep ID DATE FEB 24 2004

Conditions of approval, if any:



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

*Jim K - eng*

MARY E. JOHNSON  
Governor  
Betty Rivera  
Cabinet Secretary

Lori Wrotenberg  
Director  
Oil Conservation Division

*OK*  
*2/20/04*  
*[Signature]*

RECEIVED  
FEB 06 2004  
OCD-ARTESIA  
*utC*

Yates Petroleum Corporation  
105 South 4<sup>th</sup> Street  
Artesia, New Mexico 88210

Form C-103 Report of Plugging for your *Quiniela AXQ St. #1 - Sec 5 T10S-R26E-30-005-63363*  
Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- ☒ 1. All pits have been filled and leveled.
- ☒ 2. Rat hole and cellar have been filled and leveled.
- ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- ☒ 5. The dead men and tie downs have been cut and removed.
- ☒ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
- ☒ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

*[Signature]*  
Name  
*Delg Supra*  
Title

*date*  
*2-2-04*

\_\_\_\_\_  
Van Barton  
Field Rep. II