

CIST  
[Signature]

# OIL CONSERVATION DIVISION

2040 S. Pacheco  
Santa Fe, New Mexico 87505

**DISTRICT I**

P. O. Box 1980, Hobbs, NM 88241-1980

**DISTRICT II**

811 S. First, Artesia, NM 88210

**DISTRICT III**

1000 Rio Brazos Rd, Aztec, NM 87410

WELL API NO.  
**30-005-00424**

5. Indicate Type of Lease  
STATE  FEE

6. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
**(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL or TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)**

7. Lease Name or Unit Agreement Name  
**WHITE RANCH**

1. Type of Well:  
OIL  WELL      GAS  WELL      OTHER

8. Well No.  
**1**

2. Name of Operator  
**C. W. TRAINER**

9. Pool name or wildcat  
**WHITE RANCH MISSISSIPPIAN, (GAS)**

3. Address of Operator  
**c/o OIL REPORTS & GAS SERVICES, INC., 1008 W. BROADWAY, HOBBS, NM 88240**

4. Well Location  
Unit Letter **E** : **1980** Feet From The **NORTH** Line and **660** Feet From The **WEST** Line  
Section **34** Township **11S** Range **29E** NMPM **CHAVES** County

10. Elevation (Show whether DF, RKB, RT, GR, ect.)  
**3792' DF**

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG & ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST & CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**IT IS INTENDED TO PLUG THIS WELL AS FOLLOWS:**

**SET CIBP @ 8619' W/35' CMT ON TOP, CIRC BRINE GEL TO SURF. RUN FREEPOINT, CUT & PULL 5 1/2" CSG. 6700'+.**

**SPOT 25 SX CMT PLUG 50' IN & 50' OUT 5 1/2" CSG STUB & TAG.**

**SPOT 25 SX CMT PLUG 6750'-6650'.**

**SPOT 25 SX CMT PLUG 5695'-5595'.**

**SPOT 25 SX CMT PLUG 3405'-3305'.**

**SPOT 10 SX PLUG TO SURF.**



\* Notific N.M.O.C.D. to witness Plugging Operations.  
I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gaye Heard TITLE AGENT DATE 09/12/2000

TYPE OR PRINT NAME GAYE HEARD TELEPHONE NO. (505)393-2727

(THIS SPACE FOR STATE USE)  
APPROVED BY Mike Sheffield TITLE Field Rep II DATE 9/18/2000  
CONDITIONS APPROVAL, IF ANY: