		1 2				
NO. OF COPIES	RECEIVED	1			Form C-103	
DISTRIBU	TION	1			Supersedes Old C-102 and C-103	
SANTA FE		14		NEW MEXICO OIL CONSER THEN COMMESSION	Effective 1-1-65	
FILE						
U.S.G.S.				MAD 0 4 1070	5a. Indicate Type of Lease	
LAND OFFICE	=			MAR 2 6 1970	State X Fee.	
OPERATOR	 	1		•	5. State Oil & Gas Lease No.	
L				O. C. C.	K-6188	
		CLU	IDD:		mmmmmm	
(DO NOT	USE THIS FO	OUI	NUK' A PROF			
1.				The state of the s	7. Unit Agreement Name	
OIL WELL	GAS Wel	. \square		OTHER.	.,	
2. Name of Opera				VINER	8. Farm or Lease Name	
·						
Smith Dev	velopme	Davis State				
· ·						
Box 1000		#1				
4, Location of We					10. Field and Pool, or Wildcat	
UNIT LETTER	C			660 FEET FROM THE North LINE AND 1980 FEET FROM	Wildcat	
THE West	t .	INE e	CCT10	1 11 TOWNSHIP 4S RANGE 26E NMPM		
/#C		.ine, 5	EC 110:	NMPM		
MITTI	77777	TD.	111	15. Elevation (Show whether DF, RT, GR, etc.)	12, County	
			////	G. L. 3842	Chaves	
16.	777777	7777	-777			
		Che	ck A	ppropriate Box To Indicate Nature of Notice, Report or Ot	her Data	
	NOTIO	CE O	FIN	TENTION TO: SUBSEQUEN	T REPORT OF:	
		_				
PERFORM REMED!	AL WORK	_		PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING	
TEMPORARILY AB	ANDON]		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT	
PULL OR ALTER C	ASING]		CHANGE PLANS CASING TEST AND CEMENT JOB	. 4	
				OTHER Perset	trealment	
OTHER						
17. Describe Pro work) see R	posed or Co	mplete	id Ope	rations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed	
2011.7 522 11						
12-15-69	Spudde	ad				
	-pass.					
1-25-70	Pan &		ant.	od 41" 01# CSD assina at 12/51 m/200 am H-11/1		
1-25-70		Ran & cemented $4\frac{1}{2}$ " $9\frac{1}{2}$ # CSR casing at 1245' w/200 sx. Halliburton light wt. cmt. followed by 100 sxs. class C cement with 2% CaCl ₂ added & 1% CFR-2 added, cmt.				
					% GFR-2 added, cmt.	
	circu.	Late	d to	surface		
1-26-70 Perf. 1156-1168 - 2 holes per ft. Swb. 3 bbls. s.w./hr. with no show						
2-2-70 Set Baker Bridge Plug at 1151'.						
2-3-70	Perf/	118-	1144	. Swb. dry with no show.		
	,			· · · · · · · · · · · · · · · · · · ·		
2-4-70	Acidia	zed -	ω/50	O gals. 15% MCA Swb. dry, no show.		
			.,	b gall. 1970 hon bub, ally, no bhow.		
	P1		-1-5-	sx. from 1151 to 931.		
	TTUS V	4 T C ! !	13	ax. From 1151 to 551.		
	C ·	•	_1	* - * * - * - * - * - * - * - * - * - *		
	ement	_st	ıke_	in top.		
18. I herehu heet	fy that the	Inform	at for	bove is true and complete to the best of my knowledge and belief.		
//	A A	6 1	Ţ	//		
- 17			<i>*</i>	1/_		
\$7.11//	'[[v]]i	1.1		1/2		
SIGNED VIIII	1/1/1/	ufi	11/1	TITLE Production Manager	DATE March 19, 1970	
SIGNED VIIII	1 (" //4	uf.	11/1	TITLE Production Manager		
SIGNED WILL	7. ()	4 <u>6.</u>	n 111	OIL AND GAS INSPECT	MAR 2 6 1970	

CONDITIONS OF APPROVAL, IF ANY: