

State of New Mexico
Energy, Minerals and Natural Resources Department

Submit 3 Copies
to Appropriate
District Office

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

NOV 21 '90

WELL API NO.
30-005-62791

5. Indicate Type of Lease
STATE FFF

6. State Oil & Gas Lease No.
V-1548

7. Lease Name or Unit Agreement Name
Gulf State

8. Well No.
4

9. Pool name or Wildcat
Double L (Queen) Assoc.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG OR ABANDON A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER

2. Name of Operator
Collins Oil & Gas Corporation

3. Address of Operator
P.O. Box 2443, Roswell, NM 88202-2443

4. Well Location
Unit Letter G : 2310 Feet From The North Line and 1980 Feet From The East Line
Section 14 Township 14S Range 29E NMPM Chaves County

10. Elevation (Show whether DF, RKIB, RT, GR, etc.)
3752 GL.

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-19-90 T.D. well at 1850' Queen formation appears to be water.
Prepare to plug & abandon per verbal instructions OCD in Artesia.
1st plug 1850 - 1750' with 30 sx. cement.
2nd plug 940' - 840' with 30 sx. cement.
3rd plug 342' - 242' with 30 sx. cement. Tag top of cement.
4th plug 60' - surface ----- cement.
Fresh water gel between all plugs.
Install dry hole marker, clean location of trash & anchors, fill in pit and level location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ray D. Collins TITLE Pres. Collins O/G DATE 11-19-90

TYPE OR PRINT NAME ROY D. COLLINS TELEPHONE NO. _____

(This space for State Use) ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II TITLE _____ DATE _____

APPROVED BY _____

CONDITIONS OF APPROVAL, IF ANY: _____