

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

MAY 7 1970

O. C. C.

ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Humble Oil & Refg Co. ✓	8. Farm or Lease Name New Mexico BKS-ate
3. Address of Operator Box 1600 - Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>K</u> , <u>1256</u> FEET FROM THE <u>W</u> LINE AND <u>2314</u> FEET FROM THE <u>S</u> LINE, SECTION <u>30</u> TOWNSHIP <u>17S</u> RANGE <u>29-E</u> NMPM.	10. Field and Pool, or Wilcox Empire Abo
15. Elevation (Show whether DF, RT, GR, etc.) 3660 DF	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONED <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Permission to workover well is requested. Procedure -

1. Pull producing equipment out of hole.
2. Perf 4 1/2 csq w/ 1 shot /ft from 6204 to 6212, 6221 to 6224, and 6229 to 6233' (18 shots).
3. Set Bridge Plug @ 6250'
4. Acidize w/ 1000 gal 15% NE acid
5. Test
6. Re-acidize w/ 5000 gal 15% acid w/ unibeads if necessary.
7. Return well to producing status.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. L. Clemmer TITLE Unit Head DATE 5/1/70

APPROVED BY W. A. Gressett TITLE OIL AND GAS INSPECTOR DATE MAY 7 1970

CONDITIONS OF APPROVAL, IF ANY: