

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO RECEIVED COMMISSION

JUN 28 1976

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
----------------------------	--

5. State Oil & Gas Lease No.

E 134

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR REELEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL OR REELEN OR PLUG BACK TO A DIFFERENT RESERVOIR.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- Injection
2. Name of Operator JEM Resources Inc.
3. Address of Operator Box 648 Artesia, N. Mex. 88210
4. Location of Well UNIT LETTER L 1980 FEET FROM THE S LINE AND 660 FEET FROM THE W LINE, SECTION 4 TOWNSHIP 17 RANGE 29 NMPM.

7. Unit Agreement Name

Cave Pool Unit

8. Form of Lease Name

Cave Pool

9. Well No.

20

10. Field and Pool, or Wildcat

Cave

15. Elevation (Show whether DE, RT, GR, etc.)

3594 Gr

12. County

Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING GPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8 5/8 set at 328 & Circulated. 7 set at 2354 & cemented with 200 sacks.

T.S. shows top of cement at 930. Open hole from 2354 - 2391. Base of salt 648.

Will set 30 sacks at 2300 & shoot pipe at 930 & set 35 sack stub plug.

Set 35 sacks at 700 - 600. 35 sacks 375 - 275 & 10 sacks & Marker at top.

Hole will be loaded with mud laden fluid. Cement will be Portland type 2.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE President

DATE 6-24-76

APPROVED BY [Signature] TITLE OIL AND GAS INSPECTOR

DATE JUN 28 1976

CONDITIONS OF APPROVAL, IF ANY: