

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

**RECEIVED**  
NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

AUG 9 1976

**O. C. C.**  
ARTESIA, OFFICE

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.  
**E 4200**

**SUNDRY NOTICES AND REPORTS ON WELLS**

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL FORM C-1011 FOR SUCH PROPOSALS.

1.  OIL WELL  GAS WELL  OTHER- **Injection**

2. Name of Operator  
**JBM Resources Inc.**

3. Address of Operator  
**B ox 648 Artesia, N . Mex. 88210**

4. Location of Well  
UNIT LETTER **B** **660** FEET FROM THE **N** LINE AND **1980** FEET FROM  
THE **E** LINE, SECTION **9** TOWNSHIP **17** RANGE **29** N.M.P.M.

7. Unit Agreement Name  
**CAVE POOL UNIT**

8. Farm or Lease Name  
**CAVE POOL** *lit*

9. Well No.  
**33**

10. Field and Pool, or Wildcat  
**CAVE** *Sh. dg.*

15. Elevation. (Show whether DF, RT, GR, etc.)  
**3585 GR**

12. County  
**Eddy**

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

<p>NOTICE OF INTENTION TO:</p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>SUBSEQUENT REPORT OF:</p> <p>PLUG AND ABANDON <input type="checkbox"/></p> <p>CHANGE PLANS <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p> <p>REMEDIAL WORK <input type="checkbox"/></p> <p>COMMENCE DRILLING OPKS. <input type="checkbox"/></p> <p>CASING TEST AND CEMENT JOB <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p> <p>ALTERING CASING <input type="checkbox"/></p> <p>PLUG AND ABANDONMENT <input checked="" type="checkbox"/></p>
---	---

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

**7 5/8 Surface set at 683 & Circ. 4 1/2 set at 2489. Top perf. 2408.**

**Top Queen 1690. Base salt 655.**

**Set 15 sacks at 2360 & tagged at 2200. Shot pipe at 1791 & set 35 sacks stub plug. Set 35 sacks at 721, & 10 sacks and marker at top.**

**Hole was loaded with M. L.F. & Cement was Portland type 2.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Robert J. Lee* TITLE Pres. DATE 8-9-76

APPROVED BY B.W. Weaver TITLE OIL AND GAS INSPECTOR DATE 8-12-76

CONDITIONS OF APPROVAL, IF ANY: