

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Hondo Oil & Gas Company		8. FARM OR LEASE NAME H. E. West "A"	
3. ADDRESS OF OPERATOR P. O. Box 2208, Roswell, NM 88202		9. WELL NO. 11	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FNL & 1980' FEL		10. FIELD AND POOL, OR WILDCAT Grayburg Jackson	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 3-T17S-R31E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3972' GR		12. COUNTY OR PARISH Eddy	
		13. STATE NM	

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETION	<input type="checkbox"/>	FRACTURE TREATMENT	<input checked="" type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input checked="" type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>	(Other)	<input type="checkbox"/>		<input type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>	(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 7/28/89 Perforated 3812-3973' with 36 holes. Acidized 3812-3973' with 3000 gal. 15% NEFE acid. Swabbed well back.
- 7/29/89 Reacidized 3812-3973' with 6000 gal. 20% CRA acid. Flowed and swabbed well back.
- 8/01/89 Perforated 3601-3770' with 36 holes. Acidized 3601-3770' with 3000 gal. 15% NEFE acid. Swabbed well back.
- 8/02/89 Frac'd 3601-3770' with 25,000 gal. 30# cross-linked gel + 40,000# 20-40 sand. Swabbed well back.
- 8/05/89 Perforated 3439-3570' with 32 holes.
- 8/07/89 Acidized 3439-3570' with 3000 gal. 15% NEFE acid. Swabbed well back.
- 8/08/89 Frac'd 3435-3570' with 25,000 gal. cross-linked gelled water + 40,000# 20-40 sand. Flowed well back.

18. I hereby certify that the foregoing is true and correct

SIGNED Lisa Bohannon

TITLE Engineering Technician

DATE 8/9/89

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

*See Instructions on Reverse Side

SJS