

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN THE VICINITY OF
(Other Instructions on reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-029426-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

H. E. West "B"

9. WELL NO.

18

10. FIELD AND POOL, OR WILDCAT

Grayburg Jackson SA 2-5-SA

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 3-T17S-R31E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ WIW

2. NAME OF OPERATOR

Hondo Oil & Gas Company

3. ADDRESS OF OPERATOR

P. O. Box 2208, Roswell, NM 88202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

660' FSL & 1980' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3948' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) deepened & convert to WIW

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

6/30/89

thru Deepened hole from 3725' to new TD of 3996'.

7/06/89

7/10/89 Acidized open hole from 3716-3994' with 8000 gal. Super X Emulsion acid. Swabbed and flowed back.

7/11/89 Perforated 3386-3705' with 52 holes.

7/12/89 Acidized 3386-3705' with 6000 gal. 15% NEFE acid. Flowed and swabbed well back.

7/13/89 Reacidized 3386-3705' with 4000 gal. 15% NEFE acid. Swabbed well back. Frac'd 3386-3705' with 40,000 gal. cross-linked gelled water + 69,420# 20-40 sand. Flowed and swabbed well back.

7/18/89 Ran Guiberson Uni-VI lok-set packer and 111 jts. of 2 3/8" fiber-glass tubing. Set both @ 3310'. Ready for injection.

Post ID-2
8-25-89
Deepen

18. I hereby certify that the foregoing is true and correct

SIGNED Lisa Behannon TITLE Engineering Technician

DATE 8/4/89

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

SJS

*See Instructions on Reverse Side