O+6-BLM-Roswell, braver, DB-Engr PWS, 1-Foreman EF, 1-Laura Richardson 1-Mr. J.A. - Midland Artesia. NM 88210

| Form 9-331 Dec. 1973 | Form Approved. Budget Bureau No. 42–R1424 |
|--|--|
| UNITED STATES | 5. LEASE |
| DEPARTMENT OF THE INTERIOR | I.C-029419(1) |
| GEOLOGICAL SURVEY | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME BY |
| SUNDRY NOTICES AND REPORTS ON WELLS | 7. UNIT AGREEMENT NAMAR 26 1934 |
| (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) | 8. FARM OR LEASE NAME O. C. D. |
| 1. oil gas other | Skelly Uni ARTESIA, OFFICE |
| 2. NAME OF OPERATOR | 9. WELL NO. 23 |
| Getty Oil Company | 10. FIELD OR WILDCAT NAME |
| 3. ADDRESS OF OPERATOR | Grayburg Jackson Q-G-SA |
| P.O. Box 730 Hobbs, NM 88240 | 11. SEC., T., R., M., OR BLK. AND SURVEY OR |
| 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 | AREA |
| below.) AT SURFACE: Unit ltr. K, 1980' FEL & 1980 FWL | Sec. 14-17S-31E |
| AT TOP PROD. INTERVAL: | 12. COUNTY OR PARISH 13. STATE |
| AT TOTAL DEPTH: | Eddy New Mexico |
| 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, | 14. API NO. |
| REPORT, OR OTHER DATA | 15 ELEVATIONS (CHOW DE VOD AND |
| | 15. ELEVATIONS (SHOW DF, KDB, AND WD) 3909' DF |
| REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: | 3303 DF |
| TEST WATER SHUT-OFF X | |
| FRACTURE TREAT | |
| REPAIR WELL | (AIOTE: Paris I and I an |
| PULL OR ALTER CASING | (NOTE: Report results of multiple completion or zone change on Form 9-330.) |
| MULTIPLE COMPLETE | |
| CHANGE ZONES | |
| ABANDON* [] (other) | |
| | |
| 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinen | irectionally drilled give subsurface locations and |
| 1. Rig up pulling unit. | |
| 2. Pull rods. | OFAU OF SON |
| 3. Install BOP and pull tubing. | SUPER PARTY AND |
| 4. RIH w/B.P. | KAZ |
| 5. Run temp survey or CBL. | JAN - O E |
| 6. Squeeze water flow. | |
| 7. Drill out cmt. and recover BP. | 78 · 1997 · 5 |
| 8. Clean out to T.D. | 52 0/ST E |
| 9. Acidize w/6000 gals. 15% NEFE. | Ze, N. M |
| 10. Return to production. | Now Sylve |
| | BOWEN OF SAME SERVICE ON M. M. MEXICO |
| Subsurface Safety Valve: Manu. and Type | Set @ Ft. |
| 18. I hereby certify that the foregoing is true and correct | |
| | endent January 6, 1984 |
| - Citable | |
| APPROVED BY TITLE | DATE |
| CONDITIONS OF APPROVAL, IF ANY MAR 2 0 1981 | |
| MAN ← U TQUE | |