

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN
(Other ins
verse side)

REPLICATE

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

1-400-276

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Shelly Oil Company	8. FARM OR LEASE NAME Shelly Unit
3. ADDRESS OF OPERATOR P.O. Box 730, Hobbs, New Mexico	9. WELL NO. 103
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FWL and 1980' FWL Section 14-178-31X	10. FIELD AND POOL, OR WILDCAT Grayburg Jackson
14. PERMIT NO. ---	11. SEC., T., E., M., OR BLM. AND SURVEY OR AREA Section 14-178-31X
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3913' RT	12. COUNTY OR PARISH Hidalgo
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

Perforate and Treat

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recombination Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well is presently producing through 5-1/2"OD casing perforations 3348-3704' (intervals) in the Grayburg and San Andres formation. We plan to perforate additional holes in the Grayburg from 3324-3535' with 9 shots and treat.

1. Move in and rig up Pulling Unit.
2. Pull Tubing.
3. Perforate 5-1/2"OD casing from 3324-3525' with total of 9 shots collectively.
4. Run tubing with bridge plug and packer.
5. Isolate and acidize through new 5-1/2"OD casing perforations 3324-3525' with 1,000 gal. acid using sealers.
6. Sand-Water frac through 5-1/2"OD casing perforations 3324-3525' with 10,000 gallons Water and 10,000 sand.
7. Pull retrievable bridge plug.
8. Run tubing and rods and return well to a producing status.

18. I hereby certify that the foregoing is true and correct

SIGNED **(SIGNED) V. E. Fletcher**TITLE **District Superintendent**DATE **March 16, 1967**

(This space for Federal or State office use)

TITLE

APPROVED

MAR 21 1967

R. L. BECKMAN

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

RECEIVED
MAR 20 1967
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 5: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not called off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-685229

9-67-351

RECEIVED
MAR 30 1963
U.S. DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED
MAR 30 1963
U.S. DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT