

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN _____
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to different reservoirs.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. I-Sus-276	
2. NAME OF OPERATOR SHALLY OIL COMPANY		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P. O. Box 730 - Hobbs, New Mexico 88240		7. UNIT AGREEMENT NAME Shelly Unit	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1900' FWL & 1900' FWL Section 14-178-31E		8. FARM OR LEASE NAME Grayburg-Jackson	
14. PERMIT NO. -----		9. WELL NO. 105	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3913' DF		10. FIELD AND POOL, OR WILDCAT Section 14-178-31E	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 14-178-31E	
		12. COUNTY OR PARISH Hddy	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☒	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) Convert to water injection	X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) _____	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well is presently producing through 3-1/2" OD casing perforations 3348-3704' (intervals) in the Grayburg and San Andres formation. We plan to perforate additional holes in the Grayburg from 3324-3525' with 11 shots and treat.

1. Move in and rig up Pilling Unit.
2. Pull Tubing.
3. Perforate 3-1/2" OD casing from 3324-3525' with total of 11 shots selectively.
4. Run tubing with bridge plug and packer.
5. Isolate and acidize through new 3-1/2" OD casing perforations 3324-3525' with 1,000 gallons acid using sealers.
6. Sand-Water free through 3-1/2" OD casing perforations 3324-3525' with 10,000 gallons water and 10,000 sand.
7. Water injection equipment will be installed and water injected through 3-1/2" OD casing perforations 3324-3525' of the Grayburg Formation and perforations 3606-3704' of the San Andres Formation. This will be a water injection well for the Shelly Operated Shelly Unit.

RECEIVED

DEC 22 1967

18. I hereby certify that the foregoing is true and correct

SIGNED (ORIGINAL) V. B. Fletcher TITLE District Superintendent DATE December 19, 1967

(This space for Federal or State office use)

APPROVED BY John A. Gray TITLE District Superintendent DATE DEC 21 1967

CONDITIONS OF APPROVAL, IF ANY:

eral and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

RECEIVED
JAN 21 1964
U.S. GOVERNMENT PRINTING OFFICE
WASHINGTON, D.C.