

NM OIL CONS. COMMISS **DN**  
Drawer DD  
Artesia, NM 88210

~~ROSWELL DISTRICT COPY~~

Form 9-331  
Dec. 1973

Form Approved.  
Budget Bureau No. 42-R1424

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well ☐ gas ☐ well ☐ other ☒ WIW

2. NAME OF OPERATOR  
Sun Exploration & Production Co.

3. ADDRESS OF OPERATOR  
P.O. Box 1861, Midland, Texas 79701

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 2310 FNL & 1650/FEL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) ☐

SUBSEQUENT REPORT OF:

☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☒

RECEIVED BY  
SEP - 5 1986  
O. C. D.  
ARTESIA, OFFICE

OIL & GAS  
U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

5. LEASE LC 049998 (A)  
V.L. Foster  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
7. UNIT AGREEMENT NAME  
8. FARM OR LEASE NAME  
V.L. Foster  
9. WELL NO.  
6  
10. FIELD OR WILDCAT NAME  
Grayburg-Jackson - SR-8-G-5A  
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Unit letter "G"  
Sec. 17, T-17-S, R-31-E  
12. COUNTY OR PARISH Eddy 13. STATE New Mexico  
14. API NO.  
Federal LC 049998 (A)  
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
N/A

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- 4-2-82 Pull Rig into Loc. w/ CAT- Dig & clean out cellar, Dig workover Pit  
Install two steel matting beams.
- 4-4-82 Remove wellhead/Latch onto 2-3/8 tbg, remove slips, top collar pulled off, drop tbg approx. 3' cut new THDS on top JT tbg, unseat PKR (make unknown) after 1 hr., pull 9 jts w/ full wt tbg. PKR hung, tbg parted, pull 3 addn jts tbg, parted w/ 21' on last JT, jagged body break, last 2 JTS heavy pitted w/ large holes.
- 4-6- RIH w/ 3-7/8 overshot w/ 2-3/8 grapple, HYD JARS. 4- 3-1/16 DC's, 2-3/8 tbg. TAG & Latch fish @ 495', jarred fish loose, max pull 50,000#. POH w/ Overshot, Rec 44 JTS 2-3/8 tbg & 3' PC. 2-3/8 Body brk. Re-ran overshot, JARS DC'S, 2-3/8 Tbg. TAG & Latch fish 1575'. Jarred Fish loose, max pull 50,000#. POH, w/ over shot. Rec. 132' 2-3/8 tbg. & 145' 4 1/2" Liner, (5 JTS & 13' PC.) w/ PKR inside liner.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Dee Ann Kemp TITLE Acctg. Assist II DATE 4/28/82

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE 9-4-84  
CONDITIONS OF APPROVAL, IF ANY:

Post ID-2  
10-26-84  
PFA

