CIST

DEPARTMENT OF SUNDRY NOTICES  Do not use this form for proposals to draw Use "APPLICATION FO  SUBMIT  1. Type of Well  Well Gas Well Other  2. Name of Operator  SOCORRO PETROLEUM COMPANY  3. Address and Telephone No.  20 N. BROADMAY, SUITE 1500, OKLAHOMA  4. Location of Well (Footage, Sec., T., R., M., or Survey Description of Well (Footage, Sec., T., R., M., or Survey Description)	rill or to deepen or reentry to a different reservoir.  R PERMIT—" for such proposals  IN TRIPLICATE  O. C. D.  ARTESIA, OFFICE  CITY, OK. PHONE NO. (405) 552-4560  escription)	8. Well Name and No.  TURNER "A" 30  9. API Well No.  30-015-05228  10. Field and Pool, or Exploratory Area Fren Seven Rivers
1880' FSL & 660' FEL Section 18-T17S-R31E		11. County or Parish, State  EDDY CO., NEW MEXICO
12. CHECK APPROPRIATE BOX(	s) TO INDICATE NATURE OF NOTICE, REPOR	IT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent  Subsequent Report  Final Abandonment Notice	Abandonment  Recompletion  Plugging Back  Casing Repair  Altering Casing	Change of Plans  New Construction  Non-Routine Fracturing  Water Shut-Off  Conversion to Injection
Describe Proposed or Completed Operations (Clearly state all give subsurface locations and measured and true vertice).	Other Temporal y Abandon  CAS HG THTE GRATY  Description data, including estimated date of starting in the control of the cont	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log (org.)
Plans are to temporarly abandon this wellbore by first plugging back with sand to 1830' (approximately 50' above the top of the 5½ Liner) and then spotting 30 sacks of Class "C" cement containing 2½ CaCl in the 7" production casing @ 1820'. The top of the cement plug should be at 1660'±. After allowing the cement to set for 24 hours, the cement plug and 7" production casing will be tested to 500 psi. This test will be witnessed by a BLM representative.  In lieu of plugging the well, it is requested that it be granted a temporarily abandoned status following the above described work including the passing of a 500 psig mechanical integrity test. This wellbore is located within an active Grayburg-Jackson waterflood project and is a deepening candidate during the infill development program now being evaluated and implemented. The well's current completion interval, the Seven Rivers, also appears to have secondary recovery potential. Plugging this well would necessitate it being redrilled at a future date.		
14. I hereby certify that the foregoing is true and correct  Signed O CONTROL STATE Office use)  (This space for Federal or State office use)  Approved by Conditions of approval, if any:  — SEE ATTACHED—	Jo Ann Hooks  Title Engineering Technican  Potrolsum Engineer	Date

## BUREAU OF LAND MANAGEMENT CARLSBAD RESOURCE AREA

## Temporary Abandonment of Wells on Federal Lands

. 4

## Conditions of Approval

According to 43 CFR 3162.3-4-c, " No well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer".

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County call (505) 887-6544; for wells in Lea County call (505) 393-3612.
- 2. A bridge plug or packer shall be set at a maximum of 50 feet above any open perforations or open hole.
- 3. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- 4. The production casing shall be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leak-off.

Wells that successfully pass the casing integrity test will be approved for Temporary Abandonment (TA) status for 12 months provided that the operator:

- 1. Submits a subsequent Sundry Notice requesting TA approval,
- 2. Attaches a clear copy or the original of the pressure test chart,
- 3. And attaches a detailed justification why the well should not be plugged and abandoned.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.