N. M. O. Form 9-331 (May 1963) Form approved. ITED STATES SUBMIT IN TI (Other instruct. ICATE* Budget Bureau No. 42-R1424. DEPARTMENT OF THE INTERIOR verse side) 5. LEASE DESIGNATION AND SERIAL NO. **GEOLOGICAL SURVEY** LC 029548-A 6. IF INDIAN, ALLOTTED OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir Use "APPLICATION FOR PERMIT—" for such proposals.) 7. UNIT AGREEMENT NAME GAS WELL WELL X OTHER 2. NAME OF OPERATOR 8. FARM OR LEASE NAME Sinclair Oil & Gas Company C. A. Russell 3. ADDRESS OF OPERATOR 9. WELL NO. P. O. Box 1920, Hobbs, New Mexico 88240 NOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface 10. FIELD AND POOL, OR WILDCAT Grayburg Jackson 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 2200' from North line and 2665' from East line of Sec. 18-T17S-R31E 18-T17S-R31E 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 12. COUNTY OR PARISH | 13. STATE 14. PERMIT NO. 3746' DF 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF PULL OR ALTER CASING REPAIRING WELL WATER SHUT-OFF FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT ALTERING CASING SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING ABANDON MENT® REPAIR WELL CHANGE PLANS (Norm: Report results of multiple completion on Weil Completion or Recompletion Report and Log form.) (Other)Convert oilwell to WIW of "Sinclair Russell Grayburg-Jackson Waterflood Project".

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.)*

Reference New Mexico Oil Conservation Commission Order No. R-3185 granting approval

PROPOSE TO: Convert oilwell to water injection well as follows:

> Cleanout and set Guiberson Shorty Tension packer @ 3205 and inject water down 2-3/8"OD tubing into open hole 3280-3510'. Fill tubing casing annulus with corrosion inhibited fluid.

RECEIVED

APR 1 3 1967

C. C. C. ARTESIA, OFFICE - RECEIVED 1967 SUP

10

New Mexico

		L'EDLO MEN	
18. I hereby certify that the foregoing is true and correct	-	U.S. alesia	1. 5. 67
SIGNED My Surglolon	TITLE Engineer	PATE _	4-2-67
(This space for Federal or State office use)			7.
APPROVED BY	TITLE	DATE	·
APP 1961			

*See Instructions on Reverse Side

Orig&4cc: USGS, Artesia cc: Regional Office

cc: file