

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN 2 PLACES
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 029395 (a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Turner "A"

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT
Grayburg-Jackson11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 19, T17S, R31E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☐ OTHER ☒ WIW

2. NAME OF OPERATOR

Atlantic Richfield Company

3. ADDRESS OF OPERATOR

P.O. BOX 1978, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

330' FNL, 1980' FEL (Unit Letter B)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3660' Grd

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Run 4 1/2" Innerstring

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

To effect a more efficient injected water pattern, we propose the following work:

1. Clean out to original T.D. of 3423'.
2. Run 4 1/2" OD 8R 9.5# casing to T.D. and cement w/200 sx Class "C" cement containing 5# salt per sack.
3. Run GR-Correlation log and perforate Jackson zone w/one 0.42" jet @ 3348, 3352, 3359, 3363, 3368, 3370, 3374, 3381, 3384, 3392, 3395, 3398, 3401, 3412 and 3415' (15 holes, GR-Neutron log).
4. Treat w/2500 gallons 15% HCl acid and ball sealers.
5. Run 2-3/8" tubing w/tension packer set at about 3300'.
Resume water injection.

Work to be started about 1/5/70.

18. I hereby certify that the foregoing is true and correct

SIGNED

C.D. Bratches

TITLE Dist. Drilling Supervisor

DATE 12-10-69

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side