

# SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such.)

1. WELL ☒ GAS WELL ☐ OTHER ☐  
2. NAME OF OPERATOR ARCO Oil and Gas Company  
3. ADDRESS OF OPERATOR Division of Atlantic Richfield Company  
P. O. Box 1710, Hobbs, New Mexico 88240  
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

RECEIVED BY  
NOV 12 1985  
O. C. D.  
ARTESIA, OFFICE

5. UNIT AGREEMENT NAME  
6. FARM OR LEASE NAME  
Turner "A"  
7. WELL NO.  
17  
10. FIELD AND POOL OR WILDCAT  
Fren Seven Rivers  
11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA  
19-17S-31E

14. PERMIT NO.  
15. ELEVATIONS (Show whether LF, RT, GR, etc.)  
3620' DF

12. COUNTY OR PARISH  
Eddy  
13. STATE  
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ HOLE OR ANTER CASING ☐  
FRACURE TREAT ☐ MULTIPLE COMPLETION ☐  
SHOOT OR ACIDIZE ☐ ABANDON\* ☒  
REPAIR WELL ☐ CHANGE PLANT ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐  
FRACURE TREATMENT ☐ ALTERING CASING ☐  
SHOOTING OR ACIDIZING ☐ ABANDONMENT\* ☐  
OTHER ☐

Notes: Report results of multiple completion on Well Completion or Recompletion Report and Log forms.

17. If well is abandoned, provide additional details, including estimated date of starting any work, and if well is abandoned, provide subsurface locations and measured and true vertical depths for an markers and zones pertinent to this work.

Propose to P&A well in the following manner:

1. MIRU PU. NU BOP. POH LD CA.
2. RIH w/FBRC pkr & set @ 1775'. Test annulus to 500#. Est inj into liner. POH.
3. GIH w/CICR & set @ +1800'. Cmt liner & OH w/150 sx Cl "C". Dump 35' cmt on top. Circ w/9.5# GBW (25#/bbl swg).
4. Spot 200' cmt plug f/1300-1100' using 25 sx Cl "C". **B SALT**
5. RIH w/FBRC & set @ 600' & perf 4 holes @ 700' **530'**
6. Est inj & circ to surf out 5-1/2" x 7" annulus to surf if possible.
7. Cmt 5-1/2" csg & 5-1/2" x 7" annulus f/surf-700' using 300 sx Cl "C" neat. **530'**
8. Cut off WH. Set 4" x 4' regulation dry hole marker. Clean & restore location for abandonment.

18. I hereby certify that the foregoing is true and correct

SIGNED *Steven D. Smith*

TITLE Area Prod. Supt.

DATE 10/30/85

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE 11-8-85

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side