

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

C/SF
Open

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
811 South First, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd, Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, New Mexico 87505

WELL API NO. ✓ 30-015-05274
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-3627
7. Lease Name or Unit Agreement Name
State BK
8. Well No. 4
9. Pool name or Wildcat Grayburg Jackson, 7RVS,QN,GB,SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3618

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS).	
1. Type Of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator Mack Energy Corporation	
3. Address of Operator P.O. Box 960, Artesia, NM 88211-0960	
4. Well Location Unit Letter <u>M</u> : <u>990</u> Feet From The <u>South</u> Line and <u>906</u> Feet From The <u>West</u> Line Section <u>19</u> Township <u>17S</u> Range <u>31E</u> NMPM <u>Eddy, NM</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3618	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Mack Energy Corporation plugged and abandoned as follows:

11/16/1999 RIH w/ tbg. to 1942' set 70sx Class C 2% CC. POH to 1600' & circ. gel to surf. POH w/tbg. RIH w/wireline & tag plug @ 1652'. Perf. @ 1300'. RIH w/ 5 1/2" pkr. & pressure up to 500#. Couldn't pump into bottom of salt. Spot 50sx plug @ 1350'. POH w/pkr. RIH w/wireline & tag plug @ 1235'. Perf. @ 500' & couldn't pump into salt. Perf @ 475' & break circ out surface csg. Mix cmt 120sx & circ cmt to surface Disp. 250'.

11/17/1999 RIH & tag cmt. @ 322'. POH & spot 30' surface plug.

Install Dry Hole Marker

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Crissa D. Carter TITLE Production Analyst DATE 3/17/00

TYPE OR PRINT NAME Crissa D. Carter TELEPHONE NO (505)748-1288

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep I DATE 5-3-00

CONDITIONS OF APPROVAL, IF ANY