

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPlicate\*  
(Other instructions on reverse side)Form approved.  
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

LC 029395(b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Turner "B" SR

9. WELL NO.

9

10. FIELD AND POOL, OR WILDCAT

Grayburg Jackson

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 20-17S-31E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		RECEIVED JUL 25 1973	
2. NAME OF OPERATOR Atlantic Richfield Company			
3. ADDRESS OF OPERATOR P. O. Box 1978, Roswell, New Mexico 88201 D. C. C.			
4. LOCATION OF WELL (Report location clearly and in accordance with an asterisk in the space below.) See also space 17 below.) At surface 660' FNL, 660' FEL (Unit Letter A)			
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3710' GR		

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☒REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

This well is in waterflood area and has not responded. In an effort to increase production we propose to add perforations as follows. POH w/rods& tbg. Perforate Jackson zone 3402, 23, 24, 29, 30, 43, 44, 48, 53, 59, 67, 73, 74, 75, 76, 77, 78, 79, 80, 81 and 3482' w/1 shot/ft. Acidize perms 3402-3482' w/2500 gallons 15% HCl-LSTNE acid and return well to pumping.

RECEIVED  
JUL 20 1973  
U. S. GEOLOGICAL SURVEY  
ASTORIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Dist. Drlg. Supervisor

DATE

7/19/73

(This space for Federal or State office use)

APPROVED BY

SIGNATURES OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side