(May 1963)		mit in Licate Budget Bureau No. 42-R1424.  5. Lease Designation and Serial No.  LC 029395 (b)
	SUNDRY NOTICES AND REPORTS ON WE this form for proposals to drill or to deepen or plug back to a d Use "APPLICATION FOR PERMIT—" for such proposals.)	
OIL X GAS	S OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Atlant	cic Richfield Company	8. FARM OR LEASE NAME Turner "B"
3. Address of open P. O.	Box 1978, Roswell, N.M. 88201	9. WELL NO
4. LOCATION OF WEL See also space 17 At surface	LL (Report location clearly and in accordance with any State requi 7 below.)	rements.* 10. FIELD AND FOOL, OR WILDCAT Fren
330' F	FSL, 330' FWL (Unit letter M)	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  Sec. 20, T17S, R31E
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.	12. COUNTY OF PARISH 13. STATE
	3613' GR	Eddy N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

SUB	SEQUENT REPORT	r or:	
WATCL SHUT-OFF		REPAIRING WELL	
FRACTURE TREATMENT		ALTERING CASING	
SHOOTING OR ACIDIZING		ABANDONMENT*	
(Other) Tempora	rily Aba	ndon	x
(NOTE: Report res		completion on Well	I

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

This well has been temporarily abandoned by pulling tubing and capping well with 2000# WOG valve. T.A. 3/1/73. Well will be held for waterflood study.

RECEIVED

APR 1 o 1973

ARTUCK, OF FICE 18. I hereby certify that the foregoing is true and correct TITLE Dist. Drlg. Supervisor SIGNED (This space for Federal or State office use) APPROVED BY DATE

\*See Instructions on Reverse Side