

DEPARTMENT OF THE INTERIOR (Other Instructions on Reverse Side)  
GEOLOGICAL SURVEY

Copy to SF

Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. TA OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. LC 029395 (b)	
2. NAME OF OPERATOR Atlantic Richfield Company ✓		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P. O. Box 1710, Hobbs, New Mexico 88240		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  330' FSL & 330' FWL (Unit letter M)		8. FARM OR LEASE NAME Turner "B"	
14. PERMIT NO.		9. WELL NO. 27	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3613' GR		10. FIELD AND POOL, OR WILDCAT Fren Seven Rivers	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 20-T17S-R31E	
		12. COUNTY OR PARISH Eddy	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) Plug & Abandon ☒

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

RU 3/8/76. Installed BOP. WIH w/7" CIBP on WL to 1850'. WIH w/2-3/8" tbg to 1845', circ hole w/48 BFW w/7 sx FW gel. Spotted 35' Cl H cmt (10 sx) on top of CIBP. Stretched 5 1/2" OD csg. FP indicated @ 946'. WIH w/jet cutter on WL to 850' & shot csg. Pulled & rec 22 jts (850') of 5 1/2" OD 14# csg. Spotted 35 sx Cl H cmt across 5 1/2" OD csg stub (100' plug) @ 850'. Spotted 40 sx Cl H cmt (100' plug 557-457') across 7" csg stub & top of salt @ 527'. Spotted 10 sx cmt @ surface, installed regulation dry hole marker. Cleaned & levelled location in accordance w/USGS & BLM stipulations. P&A eff 3/11/76. Your office to be notified when location is ready for inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Dist. Drig. Supv.

DATE 3/23/76

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side