

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TR. CATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 029395 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Turner "B"

9. WELL NO.

78

10. FIELD AND POOL, OR WILDCAT  
Grayburg Jackson11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

20-T17S-R31E

12. COUNTY OR PARISH  
Eddy13. STATE  
New Mexico

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

SINCLAIR OIL &amp; GAS COMPANY

3. ADDRESS OF OPERATOR

P. O. Box 1920, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

2080' fr the South line and 1980' fr the East line

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3688' GR

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other) Convert oilwell to WIW

X

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other)

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

TD Drilled 3600'. PBTD 3570'. Presently producing from Grayburg Jackson perfs.  
3044-3100' 8 BOPD and 0 BWPD.PROPOSE TO: Perforate Grayburg Jackson GR-N Collar log w/2-3/8" jet shots @ approx.  
3421, 25, 33, 35, 37, 42 & 68'. Acidize w/approx. 1000 gals. breakdown  
acid. Run 2-3/8"OD tubing and packer set @ approx. 2971'. (Load  
annulus w/inhibited water). Convert from oilwell to water injection  
well in Grayburg Jackson perfs. 3044-3468' in Russell-Turner Waterflood  
Area.RECEIVED  
NOV 2 1967  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Engineer

DATE

10-31-67

(This space for Federal or State office use)

APPROVED BY

TITLE

DISTRICT ENGINEER

DATE

NOV 2 1967

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

Orig & 4cc: USGS, Artesia, N.M.  
cc: Regional Office  
cc: file