## State of New Mexico , Minerals and Natural Resources Department En.

Form	(	]-	1	0.	3
Revise	d	1-	1	-8	

	DISTRICT I P.O. Box 1980, Hobbs, NM	88240
--	--	-------

DISTRICT II P.O. Drawer I

OIL CONSERVATION DIVISION

P.O. Box 2088

WELL API NO. 30-015-05310 5. Indicate Type of Lease

SUBSEQUENT REPORT OF:

P.O. Drawer DD, Artesia, NM 88210	J	Santa Fe, New Mexico 87504-2088		ST ST	TATE 📙	FEE 🔀
DISTRICT III		,		6. State Oil & Gas	Lease No.	
1000 rio Brazos Rd, Aztec, NM 87410				LC-029395-B		
(DO NOT USE THI	IS FORM FOR PROPOSAL DIFFERENT RESERVOIR.	AND REPORTS ON WELLS  S TO DRILL OR TO DEEPEN OR PLUG BACK TO USE "APPLICATION FOR PERMIT" OR SUCH PROPOSALS.)	O A	7. Lease Name or 1 Turner B	Unit Agreeme	ent Name
1. Type of Well Oil Well Gas Well	Other WIW					
2. Name of Operator				8. Well No.		
DEVON ENERG	Y CORPORATION (NEVA	DA)		41		
3. Address of Operator				9. Pool name or W	ildcat	
20 NORTH BRO	ADWAY, SUITE 1500, OK	LAHOMA CITY, OKLAHOMA 73102 (405) 235-3	3611	Grayburg Jacks	son	
4 Well Location						
Unit Letter F:1650	Feet From The North	Line and <u>1650</u>	Feet I	From The West	Line	
Section 20	Township 17S	Range 31E	NMPM	Eddy	County	,,,,,,,,,,
		10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3634' GR				

				the state of the state of the state of the state of		and work   CEE DITT E 1102	
OTHER: shut off water flow on surface casing			OTHER:				
PULL OR ALTER CASING				CASING TEST AND CEMENT JOB			
TEMPORARILY ABANDON		CHANGE PLANS		COMMENCE DRILLING OPNS.		PLUG AND ABANDONMENT	
PERFORM REMEDIAL WORK		PLUG AND ABANDON		REMEDIAL WORK	Ш	ALTERING CASING	Ш

Check Appropriate Box To Indicate Nature Of Notice, Report, Or Other Data

- 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RUL

NOTICE OF INTENTION TO:

١.	Perf 4 holes @ 1700' at top of cement.
2.	Break circulation to attempt to bring cement back to surface. If not successful in bringing cement back to surface, then we will run cement bond log to find top of cement. Will contact OCD before continuing with any other procedure.
3.	After finding top of cement will perf and bring cement to top of surface.
4.	RIH and put well back on injection.
he	reby certify that the information above is true and complete to the best of my knowledge and belief.
	February 1 2001
	TELEPHONE NO. (505) 749 2271
_	E OKT KINT-WAIVE JULY Manions
۱рр	roved by Walsfield TITLE Field Rg. II DATE 1/1/2001 ditions of approval, if any:
	マン・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・