UNITED STATES	EF & LG 1 - File Form Approved. Budget Bureau No. 42-R1424
DEPARTMENT OF THE INTERIOR	5. LEASE LC-029419(A)
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS o not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME Skelly Unit
servoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME APR 1 5 1983
l.oil gas ⊠ other Dual inj. well	9. WELL NO. O. C. D.
2. NAME OF OPERATOR	54 ARTESIA, OFFICE
Getty Oil Company V	10. FIELD OR WILDCAT NAME
ADDRESS OF OPERATOR	Grayburg Jackson & Fren 7-Riv
P.O. Box 730 Hobbs, NM 88240	11. SEC., T., R., M., OR BLK. AND SURVEY OR
 LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 	AREA Sec 22-17S-31E
AT SURFACE: Unit 1tr. L 1980' FSL & 660' FWL AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE Eddy NM
AT TOTAL DEPTH:	14. API NO.
. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA EQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3828' DF
ACTURE TREAT HOOT OR ACIDIZE PAIR WELL JLL OR ALTER CASING ULTIPLE COMPLETE HANGE ZONES BANDON* Ther)	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner	firectionally drilled give subsurface to
1. Rig up pulling unit.	
2. Install BOP. 3. Pull short and long string	
3. Pull short and long string. 4. Run GR-CNL.	
	IDDIF(CELV)
5. Reperforate 7-Rivers	$\mathbf{U}_{\mathbf{U}}$
5. Reperforate 7-Rivers	APR 1 1 1983
5. Reperforate 7-Rivers 6. Acidize Grayburg 7. Acidize 7-Rivers. 8. Clean up well.	
5. Reperforate 7-Rivers 6. Acidize Grayburg 7. Acidize 7-Rivers. 8. Clean up well. 9. Run tbg. & pkrs.	· -
5. Reperforate 7-Rivers 6. Acidize Grayburg 7. Acidize 7-Rivers. 8. Clean up well.	DN 8 873
5. Reperforate 7-Rivers 6. Acidize Grayburg 7. Acidize 7-Rivers. 8. Clean up well. 9. Run tbg. & pkrs.	· -
5. Reperforate 7-Rivers 6. Acidize Grayburg 7. Acidize 7-Rivers. 8. Clean up well. 9. Run tbg. & pkrs.	ONL A CIS MINERALS MODIAL STRACE ROSWELL, NEW MEXICO
5. Reperforate 7-Rivers 6. Acidize Grayburg 7. Acidize 7-Rivers. 8. Clean up well. 9. Run tbg. & pkrs. 10. Return to inj.	ONL A CIS MINERALS MODIAL STRACE ROSWELL, NEW MEXICO

APR 13 1983