Form 9–331 (May 1963)	UNITED STATES SUBMIT IN TRIPLICATES (Other instruction on re-				re-	Form approved. To De Budget Bugeau No. 42-R1424.			
	DEDARTM TOF THE INTERIOR worse side)					LEASE DESIGNATION AND SERIAL NO.			
GEOLOGICAL SURVEY N. M. O. C. C. JOPY						LC - 029419 (A)			
SUNDRY NOTICES AND REPORTS ON WELLS						IF INDIAN, ALLOTTI	E OR TRI	BE NAME	
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)						N			
ī	USE ATTIMONT		or such proposition,		——————————————————————————————————————	UNIT AGREEMENT N	AMB	· · ·	
OIL X GAS WELL	OTHER		REGEL	VED		Skelly (· 7 - 3	1 F. 5 S	
2. NAME OF OPERATOR					8.	FARM OR LEASE NA		<u> </u>	
Getty Oil (Company		4.10 A M	1077	-		7		
3. ADDRESS OF OPERATOR			AUG 17	1311	9.	WELL NO.	<u> </u>	N. gr	
P. O. Box	730; Hobbs,	New Mexico 88	3240			53 % 2	- 33	. <i>i</i>	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface ARTESIA, OFFICE						10. FIELD AND POOL, OR WILDCAT			
At surface ARTESIA, UPPICE				I	Grayburg-Jackson 11. sec., T., R., M., OR BLK. AND				
to 1000 PRT 1000 PRT						SURVEY OR AREA			
Unit K, 1980 FSL and 1980 FWL						22-17S-31E			
14. PERMIT NO.	<u> </u>	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3843 DF			12.	COUNTY OR PARIS	H 13. ST	ATE	
	İ					Eddy	New	Mexico	
16.	CL LA		· ·	D				7.,,	
	• •		licate Nature of Notic			<u> </u>			
	NOTICE OF INTENTI	ON TO:		SUB	SEQUENT	REPORT OF:	ج الله الله الله الله الله الله الله الل		
TEST WATER SHUT-O	FF PU	LL OR ALTER CASING	WATER SI	HUT-OFF		REPAIRING	WELL :	<u>- </u>	
FRACTURE TREAT	<u> </u>	LTIPLE COMPLETE		TREATMENT		ALTERING (_	
SHOOT OR ACIDIZE	<u> </u>	ANDON*	<u>-</u>	OR ACIDIZING		ABANDONMI	NT.		
REPAIR WELL (Other) XXX-]		ANGE PLANS	(Other) (No	TE: Report res	ults of m	ultiple completion	on Well	 =	
17 NUMBER UNABARRA	Bring cemen	TIONS (Clearly state all	pertinent details and gi	ve nertinent de	tes inclu	Report and Log for ding estimated da	te of star	rting any	
proposed work. If nent to this work.)	well is directions	dly drilled, give subsur	face locations and measur	ed and true ver	rtical dep	ths for all marker	s and sor	nes perti-	
							·	- <u>9</u>	
] <u> </u>	. i. 📆	
l. Pull i	rods and tul	bing.						· · · ·	
2. Run cement bond log.									
3. Perforate and bring cement aove top of 7-Rivers.							<u>*</u>	, <u>E</u>	
4. Run temperature survey.									
5. Rerun rods and tubing.6. Place well back on production.						2		3 T.	
							_ \$ 1.		
						IEL	3	독표 (표	
				-(-EI	JED 1917 SURVEY OGICAL SURVEY A. NEW MEXICO	j 9		
				QE'		1017		• 1-	
				1,-	او ي.	Dis inter			
					$ u_{\Omega / \alpha}$.	SUNCO	-		
					Sent	OCION MENI	- E		
				11.	S. Grail	V Mr.			
				, ,	ARILL		<u>.</u>	. •	
							Ē.	· .	
					- "			•	
18. I hereby certify that	the foregoing to 4	rue and correct						· · · · · · · · · · · · · · · · · · ·	
SIGNED SIGNED	WACL	was riti	LE Area Superi	ntendent	<u>_</u>	DATE Augu	ust 9,	1977	
(This space for Fede	ral or State office	use)							
APPROVED BY	(i)	TIT)	LE			DATE	: ;	<u> </u>	
CONTINIONS OF APPROVAL, IF ANY:							: -		
$\langle \mathcal{O}^{\mathbb{Q}^2} \rangle$	•				•	िस्ट [‡] ।	,s.*		

*See Instructions on Reverse Side