Form 3160-5 (November 1983) (Formerly 9-331)

OIL.

14. PERMIT NO.

16.

2. NAME OF OPERATOR

The Wiser Oil Company 3. ADDRESS OF OPERATOR

TEST WATER SHUT OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

4. LOCATION OF WELL (Report location clearly and in accordance with any State requ

13160-5 ember 1983) nerly 9-331)	EPARTME	ITED STATES NT OF THE INTE F LAND MANAGEMI		(Other Instructions or)	M W Isi:	Dily Distan 20. 1004-01 Grand Avenue 985 EAN MSI 88210 AND SER LC-029419-A		
	is form for propos	ES AND REPOR als to drill or to deepen or plug TION FOR PERMIT - " for su	g back to a d	ifferent reservoir.	6.	F INDIAN, ALLOTTEE OR TRIB	E NAME	
OIL GA	s ot	HER WIW			7	INIT AGREEMENT NAME Skelly Unit		
NAME OF OPERATOR						8. WELL NO.		
The Wiser Oil Co	mpany /	42						
ADDRESS OF OPERATOR						9. API WELL NO.		
P.O. Box 2568 Hobbs, New Mexico 88240 (505) 392-9797						30-015-05356		
LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)						10. FIELD AND POOL, OR WILDCAT Grayburg Jackson 7-Rivers-QN-GB-SA		
At surface						11. SEC., T., R., M., OR BLK. AND		
660' FNL & 1880' FEL Unit B						Survey or area Sec. 22-T17S-R31E		
PERMIT NO. 15. ELEVATIONS (Show whether DF, 1			ether DF, R7	T. GR. etc.)		COUNTY OR PARISH	13. STATE	
FERMIT NO.	,	3875' DF	,	.,,		Eddy County	NM	
	Check Ap	propriate Box to indica	te Nature	of Notice, Report, or Othe	er Da	ata		
NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:				
ST WATER SHUT OFF		PULL OR ALTER CASING		WATER SHUT-OFF	[.	REPAIRING WELL		
ACTURE TREAT		MULTIPLE COMPLETE	\sqcup	FRACTURE TREATMENT	}-	ALTERING CASING	\vdash	
OOT OR ACIDIZE		ABANDON*		SHOOTING OR ACIDIZING	3	ABANDONMENT *		
AIR WELL CHANGE PLANS (Other)(N					(Note: Report results of multiple completion on Well			
ther) Return well to injection				Completion or Recompletion Report and Log form.)				
SCRIBE PROPOSED O	OR COMPLETE	OPERATIONS: (Clearly sta	ate all pertine	ent details, and give pertinent dates	s, incl	uding estimated date of starting any	•	
proposed work. If well i	s directionally dri	lled, give subsurface locations	and measur	ed and true vertical depths for all n	mark a	ers and zones pertinent to this work.)	1	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinen proposed work. If well is directionally drilled, give subsurface locations and measured

Wiser request approval to return well to injection by the procedure listed below. The intent will be to change from dual injection to single injection into Fren 7-Rivers. Will plug back Grayburg Jackson.

1. MIRU. TIH w/pkr. & set @ 2250'

(Other) Return well to injection

- 2. Pressure test the casing to 500#
- 3. If the casing holds POH w/pkr
- 4. TIH w/CIBP & set @ 2500'
- 5. Perforate f/2178',79',89',94',98'-2200',83',85',95',2307',23',26',42',44',98' & 2400'
- 6. TIH w/pkr. & 2-3/8" IPC tbg.
- 7. Acidize w/2000 gals, acid w/rock salt as diverter
- 8. Flow well back.
- 9. Place well on injection.



8. I hereby certify that the foregoing is true and correct.		
SIGNED Mike Jones TITLE	Production Superintendent	DATE September 26, 2001
(This space for Federal or State office use)	PETROLEUM ENGINEER	033157.2091
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:		DATE