Form 3160-5 (November 1983) (Formerly 9-331)

UNITE. TATES DEPARTMENT OF THE INTERIOR

Oil Cons.

BUREAU OF LAND MANAGEMENT

1 No. 1004-0135 C\S reverse sidertesia. NM 88210

BONEAGO EAN	J WATER TO LIVE TO THE TOTAL THE TOTAL TO TH	7 (1 100)	5. LEASE DESIGNATION AND	SERIAL NO.
OUNDRY NOTICES AND DEPORTS ON WELLS			LC-029418-B 4/9-A 6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.			O. II INDIAN, ALEXTILL OK I	KIDE WANE
Use "APPLICATION FOR PERMIT - " for such proposals.)				
OIL GAS OTHER			7. UNIT AGREEMENT NAME Skelly Unit	
WELL WIW			Skelly Ollit	
2. NAME OF OPERATOR			8. WELL NO.	
The Wiser Oil Company			46	
3. ADDRESS OF OPERATOR			9. API WELL NO. 30-015-05357	
P.O. Box 2568 Hobbs, New Mexico 88240 (505) 392-9797			10. FIELD AND POOL, OR WILDCAT	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)			Grayburg Jackson 7-Rivers-QN-GB-SA	
At surface			11. SEC., T., R., M., OR BLK. AND	
1980' FNL & 560' FEL			SURVEY OR AREA Sec. 22-T17S-R31E	
Unit H			Sec. 22-11/S-R311	2
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)			12. COUNTY OR PARISH	13. STATE
	3866' DF		Eddy County	NM_
16. Check Appropriat	e Box to indicate Natu	re of Notice, Report, or Other	er Data	
NOTICE OF INTENTION TO:			BSEQUENT REPORT OF:	
TEST WATER SHUT OFF PULL OR	ALTER CASING	WATER SHUT-OFF	REPAIRING WEI	T
FRACTURE TREAT MULTIPL	LE COMPLETE	FRACTURE TREATMENT	ALTERING CASI	NG
SHOOT OR ACIDIZE ABANDO	N*	SHOOTING OR ACIDIZING	G ABANDONMENT	r* <u> </u>
REPAIR WELL CHANGE	PLANS	(Other) Perforate Grayb	ourg .	
(Note: Report results of multiple completion				
(Other) Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any				
 DESCRIBE PROPOSED OR COMPLETED OPERA' proposed work. If well is directionally drilled, give s 	FIONS: (Clearly state all pert subsurface locations and mea:	tinent details, and give pertinent dates sured and true vertical depths for all r	s, including estimated date of starting markers and zones pertinent to this wo	any ork.)
2/19/02 MIRU Key Well Service. ND WH Isolate short string. R	UEOP. POH w/70 jts. 1.660 IPC	tbg. (2225.86') & Otis J-Latch seal assemble	ly.	
2/20/02 RU to pull long string. POH w/70 jts. 1.660 IPC tbg. (223	151'), 4-1/2" Otis dual D.T.S. ter	nsion pkr., 2-3/8" 8rd pin x 1.66 C.S.C.B. h	ydril box, 26 jts. 2-3/8" IPC XPC tbg. (834.)	96') & 2-3/8" x 4-1/2"
Howco R-4 pkr. RU BOP. RIH w 3-7/8" cone bit, 4-1/2" scraper & bit sub on 2-3/8" tbg. to 3200'. Tag scale & worked to 3235'. POH w/2-3/8" tbg. LD 4-1/2" scraper. RIH w/ 3-7/8" cone bit, bit sub				
& 2-3/8" tbg. to 3235'. Could not work down. Pull up to 2200'				
2/21/02 RU ABC reverse unit.			P. H	
2/22/02 POH w/2-3/8" IPC tbg. LD bit & sub. RJH w/3-1/2" cutri				
2/25/02 RIH & tag fill @ 3365'. Wash to 3500'. Tag pkr. & cut it 2/26/02 RU Signal WL. RIH w/4-1/2" CIBF. Could not get past 3	court. Wash to 3691'. Circulate he	ole clean. POH w/2-3/8" tbg. LD DC 8 & 1	(0018) '	58' & 85'-87' RD WI.
2/26/02 RU Signal WL. RIH w/4-1/2" CIBP Could not get past 3 RIH w/2-3/8" x 4-1/2" R-4 pkr., 25 jts. 2-3/8" IPC XPC ti				
pkrs. Test esg. annulus to 500# for 30 min. Held. RD BC		in plate to 7 july 2 5/6 in a togge solvent plate	@	•
2/27/02 RDMO. Place well back on injection – 300 BWPD @ 140				
,				
18. I hereby certify that the foregoing is true and correct.		- ACCEPTED FOR	RECORD	
			7. 2002	
SIGNED Many So Turn	TITLE Production	Tech II	DATE May 7, 2002	
Mary Jo Turner (This space for Federal or State office use)	<u>~</u>		2002	
(Time space for Federal of State Office use)		Λ Δ		
APPROVED BY	TITLE	AI EXIS C. SW	ORCAA	<u> </u>
CONDITIONS OF APPROVAL, IF ANY:		PETROLEUM EN	iGIN: LR	
and the second	*See Instruction	on On Reverse Side		

