

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPL  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

**LC-029418 (B)**

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

-----

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

**SKELLY OIL COMPANY**

3. ADDRESS OF OPERATOR

**P. O. Box 730 - Hobbs, New Mexico 88240**

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*

See also space 17 below.)  
At surface

**1980' FSL & 660' FSL of Sec. 23-17S-31E**

7. UNIT AGREEMENT NAME

**Skelly Unit**

8. FARM OR LEASE NAME

**Skelly Unit**

9. WELL NO.

**70**

10. FIELD AND POOL, OR WILDCAT

**Grayburg-Jackson**

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

**Sec. 23-17S-31E**

14. PERMIT NO.

-----

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

**3881' DF**

12. COUNTY OR PARISH

**Eddy**

13. STATE

**New Mexico**

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

|  |
|--|
|  |
|  |
|  |
|  |
|  |

PULL OR ALTER CASING

|  |
|--|
|  |
|  |
|  |
|  |
|  |

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

|  |
|--|
|  |
|  |
|  |
|  |
|  |

REPAIRING WELL

|  |
|--|
|  |
|  |
|  |
|  |
|  |

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other)

**Wash over stuck tubing**

**X**

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Moved in and rigged up pulling unit. Latched onto 2-3/8"OD tubing; unable to pull loose. Free Point Indicator Found tubing free at 3765'. Cut tubing off at 3760', leaving 81' in hole. Pulled cut-off tubing. Reran tubing with wash pipe and washed over stuck tubing from 3760' to 3874'. Pulled out of hole with fish inside wash pipe. Rm rods and tubing. Put well back on production, testing 10 barrels of oil per day.

RECEIVED

MAR 20 1968

18. I hereby certify that the foregoing is true and correct

SIGNED

(ORIGINAL)

**V. E. Fletcher**

TITLE

**District Superintendent**

DATE

**March 18, 1968**

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

**APPROVED**  
MAR 19 1968  
R. L. [Signature]  
[Signature]

\*See Instructions on Reverse Side

## Instructions

**General:** This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

**Item 4:** If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

**Item 17:** Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.