Form 9-331 May 1963)	DEPART	UNITED STATES MI : OF THE INT	ERIOR	SUBMIT IN TRIF (Other instruction verse side)	ne-on re-	5. LEASE DESIGNATION	ON AND SE	62 R1424. RIAL NO.
		GEOLOGICAL SURVE	Y 1.	M. O. C.	<u>್. Cq</u>	PYLC - 0294.		IBE NAME
(Do not us	SUNDRY NO	ICES AND REPORT	TS ON plug back to such proposal	WELLS a different reserve	olr.	7. UNIT AGREEMENT	11-11-11-11-11-11-11-11-11-11-11-11-11-	
V 1701	GAS OTHER		REU			Skelly U	nÎt	<u> </u>
2. NAME OF OPER			AUJ	17 1977		B. FARM OR LEADING		\$ T
3. ADDRESS OF OF				. C. C.		9. WELL NO.	Name Name	0. 15 15 15 15
4. LOCATION OF W See also space At surface	VELL (Report location	New Mexico 88244 clearly and in accordance wit	th anyAstase	Pegvirenten en i		Grayburg- 11. SEC., T., R., M., SURVEY OR A	Jackso	n .
•							7-31	STATE
14. PERMIT NO.		15. ELEVATIONS (Show whe		R, etc.)		12. COUNTY OR PAR	N.	Mex_
		3863						
16. TEST WATER FRACTURE TR	NOTICE OF INT	Appropriate Box To Indicention to: PULL OR ALTER CASING MULTIPLE COMPLETE	cate Natur	WATER SHUT-OFF	SUBSEQU MENT	REPAIRI	NG WELL IG CASING	
SHOOT OR AC	coize	CHANGE PLANS Ement above ferm		Completion	port results or Recomp	s of multiple complet eletion Report and Lo	ion on We	tarting in
proposed v nent to this	MOLE II MCH TO GIVE	ement above territ	ce locations	and measured and	true vertic	al depths fer all ma	rkers and	zones peru
Perf	forate 4½ csg	. @ 3099.				All and a second of the second		z E (
4. Run (7-1 5. Dril	squeeze pkr. R top @ 2180' 11 out and ru	n temperature log.		above top o	of Fren	- / Rivers	romat	1011 - 1012 - 1013 - 1013 - 1013 - 1013 - 1013
6. Ren 7. Put	un tubing and well back on	production.				in action of the control of the cont		
					R	ECEIVE	ED	
						AUG 10 197	•• • •	
					IJ.Ş	GEOLOGICAL SI	JR ŸEY	

18. I hereby certiff that the foregoing is true and correct	TITLE Area Superintendent	DATE August 9, 1977
(This space for Federal or State office use)	2	DATE
CONDITIONS OF APPROVAL, IF ANY:	TITLE	

*See Instructions on Reverse Side