

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division
811 S. 1st Street
Artesia, NM 88210-2834
SUBMIT IN TRIPlicate *
(One in instructions on
reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

C/SF

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL ☐ GAS ☐ OTHER ☐
WELL WELL Injection

2. NAME OF OPERATOR
The Wiser Oil Company

3. ADDRESS OF OPERATOR
P.O. Box 2568 Hobbs, New Mexico 88241

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements)
See also space 17 below.)
At surface

650' FSL & 2087' FWL Unit N

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3870' KB

5. LEASE DESIGNATION AND SERIAL NO.

LC-029420 (A)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Skelly Unit

8. FARM OR LEASE NAME

9. WELL NO.

30

10. FIELD AND POOL, OR WILDCAT

Grayburg-Jackson 7RVS

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 15-T17S-R31E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16. Check Appropriate Box to indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT OFF ☐

PULL OR ALTER CASING ☐

FRACTURE TREAT ☐

MULTIPLE COMPLETE ☐

SHOOT OR ACIDIZE ☐

ABANDON* ☐

REPAIR WELL ☐

CHANGE PLANS ☐

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

REPAIRING WELL ☐

FRACTURE TREATMENT ☐

ALTERING CASING ☐

SHOOTING OR ACIDIZING ☐

ABANDONMENT* ☒

(Other) Injection

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

7/ 01/96 MIRU well service. ND WH & sting out of pkr. w/short string. NU BOPE & Environmental recovery unit.
POH w/2-1/16" short string. POH w/long string, paralld pkr. & 2-3/8" tbg. Left 28 jts. 2-3/8" tbg. & AD-1
pkr. in hole.

7/02/96 GIH w/4-11/16" overshot on 2-7/8" tbg. Tagged @ 2072'. POH w/no recovery. PU 4-3/4" shoe, 2 jts. 4-1/2"
wash pipe & 2-7/8" workstring. Tagged @ 2050'. PU swivel & circ. gas & oil off. Water started coming up
around WH. RD swivel & pulled 5 stands to 1740'.

7/03/96 RIH w/shoe & wash pipe to 2065'. Try to circ. conventional. Water coming out around WH. Dry drill to 2149'.
Made three trips w/4-11/16" overshot, 3-1/16" graphel & 8' extensions on 2-7/8" workstring. Recd. 2 jts. tbg.
& 2 pieces of tbg. Top of fish @ 2127'.

7/08/96 GIH w/overshot & 2-7/8" work string. Tagged @ 2127'. Tried to catch fish. POH w/no recovery. GIH w/fluted
GS, overshot extensions & work string. Work to 2156'. POH w/no recovery. LD 2-1/16" tbg. Preparing to P & A.
Ran bit & scraper to 2100'

18. I hereby certify that the foregoing is true and correct.

SIGNED Mary Jo Turner

TITLE Production Department

Date July 16, 1996

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

ORIG. SGD. DAVID R. GLASS

*See Instruction On Reverse Side