STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

we. or torics acclived	T	
DISTRIBUTION		
SANTA FE	V	
FILE	V	V
U.S.G.S.		
LAND OFFICE		
PERATOR		

2. Name of Operator

4. Location of Well

3. Address of Operator

OIL CONSERVATION DIV P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

JUN	3	Ø	1982
-----	---	---	------

Form	C - 1	103	
Revi	sed	10-	1 - 7

Su. Indicate Type of Lease

Grayburg Jackson

U.S.O.S. 9014 3 U 1982	State X Fee
O. C. D.	5, State Oil 6 Gas Lease No. 8514-89563-B-1266
SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS OF NOT USE THIS FORM FOR PROPOSALS TO PERMIT OF PERM	
other- Injection	7. Unit Agreement Name
me of Operator Tenneco Oil Company	8. Farm or Lease Name G.J. West Coop Unit
dress of Operator 6800 Park Ten Blvd., Suite 200 North San Antonio, TX 78213	9. Well No.
	10 Field and Pool or Wildcat

1980

29-E

15. Elevation (Show whether in 3550 GR	DF, RT, GR, etc.)	12. County Eddy	
Check Appropriate Box To Indicate N NOTICE OF INTENTION TO:	ature of Notice, Report or Othe SUBSEQUENT		F:
PERFORM REMEDIAL WORK PLUC AND ABANDON CHANGE PLANS OTHER	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER TEMPORARILY Aban	PLU	TERING CASING UG AND ABANDONMENT

North

17-S

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1. Rig up pulling unit.
- 2. Nipple down injection head.
- Nipple up 5000 psi BOP's.
- Unseat packer and pull 2105' of 2-3/8" tubing.

660

- TIH and set retrievable bridge plug at 2000'. 5.
- Displace hole with treated water. POOH. Completely fill production casing with treated water. Pressure tested casing to 500 psi for 5 minutes. It held.
- Nipple down BOP's. 7.
- Nipple up injection head.
- Rig down pulling unit.

18. Thereby certify that the information above is true and complete the foliated Mutture	Production Engineering Supver.	6/21/82
APPROVED ON Mile William		JUL 1 2 1982